

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21010058/R1PA3Q2

Date:

29/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0000795_01

Claimant Vehicle No : SLX6129E**Insured Vehicle No :**

PC7125Y

Date of Loss: 25/09/2021

Nature of Claim:

TP

Claim No:

MFL2021D0004185

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLX6129E**

Make & Model: MAZDA 3, 1.5 SEDAN AT LED EU6 (A)

Engine No: P520492148

Reg. Date: 02/04/2018 (Man. Year: 2017)

Chassis No: JM6BN22A8J0200617

Colour: Brown

Odometer: 71432 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,097.20	3,914.20	2,183.00	35.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,120.00	1,390.00	55.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,607.20	5,034.20	3,573.00	41.51
Approved Total (Overridden) (S\$)		4,000.00		

(S\$)	8,607.20	4,000.00	4,607.20	53.53
+ GST 7.00/7.00% (S\$)	602.50	280.00	322.50	53.53
Nett Amount (S\$)	9,209.70	4,280.00	4,929.70	53.53
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,987.45		

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 28/09/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
 38 Toh Guan Road East, #01-57, Enterprise Hub
 Singapore 608581

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2021)
Parts:	143	MAZDA 3 1.5 SEDAN AT LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6129E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTER GRILLE TOP PANEL	Deformed	330.00 FL	*330.00 FL
2	1		*CENTER GRILLE TOP INNER PANEL GARNISH	Cracked	96.00 FL	*96.00 FL
3	1		*CENTER GRILLE ASSY	Cracked	589.00 FL	*450.00 FL
4	1		*CENTER GRILLE LOGO BADGE BASE	Cracked	22.00 FL	*22.00 FL
5	1		*CENTER GRILLE LOGO BADGE	Cracked	62.00 FL	*62.00 FL
6	2		*CENTER GRILLE LOWER SIDE OUTER CHROME (LH/RH)	Cracked	384.00 FL	*384.00 FL
7	2		*CENTER GRILLE LOWER SIDE OUTER CHROME BASE LH/RH	Cracked	42.00 FL	*42.00 FL
8	2		*CENTER GRILLE INNER SIDE TOP BRACKET LH/RH	Cracked	56.00 FL	*56.00 FL
9	1		*FRONT BUMPER	Deformed	867.00 FL	*867.00 FL
10	1		*FRONT BUMPER SIDE BRACKET LH/RH	O/S Necessary	40.00 FL	*20.00 FL
11	1		*CAR PLATE BASE GARNISH	Cracked	75.00 FL	*50.00 FL
12	1		*FRONT BUMPER LOWER GRILLE SIDE COVER RH	Missing	37.00 FL	*37.00 FL
13	1		*FRONT REINFORCEMENT	Bent	503.00 FL	*444.00 FL
14	1		*BOOT LID	Not Necessary	1,006.00 FL	*- FL
15	1		*BOOT LID LOCK	Not Necessary	161.00 FL	*- FL
16	1		*BOOT LID EMBLEM MAZDA 3	Not Necessary	57.00 FL	*- FL
17	1		*BOOT LID EMBLEM SKYACTIV	Not Necessary	67.00 FL	*- FL
18	1		*BOOT LID LOGO BADGE	Not Necessary	79.00 FL	*- FL
19	1		*REAR BUMPER	Deformed	997.00 FL	*997.00 FL
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	76.00 FL	*- FL
21	1		*REAR BUMPER TOWING COVER RH	Missing	18.00 FL	*18.00 FL
22	1		*REAR REINFORCEMENT	Bent	565.00 FL	*498.00 FL
23	1		*END PANEL	Not Necessary	531.00 FL	*- FL
24	1		*END PANEL TOP GARNISH	Not Necessary	90.00 FL	*- FL
25	2		*REAR REVERSE SENSOR LH/RH	Not Working	326.40 FS	*200.00 FS
26	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
27	1		*CENTER GRILLE CLIPS	Necessary	35.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT BUMPER RIVETING	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
30	1		*END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
31	1		*COOLANT	Not Necessary	60.00 FS	*- FS
32	1		*FRONT CAR PLATE NUMBER	Cracked	35.00 FS	*35.00 FS
33	1		*FRONT REFORCEMENT FRONT GARNISH	Cracked	71.00 FL	*71.00 FL
34	1		*CENTER GRILLE INNER TOP SIDE BRACKET RH (FEMALE)	Necessary	5.00 FL	*5.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,462.40	4,804.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,365.20	889.80
Total Parts (\$)	6,097.20	3,914.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	500.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY & RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,200.00	500.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	0.00
4	TO REMOVE /REFIX /REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	60.00
5	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	60.00	60.00
6	TO REMOVE AND REFIT REAR SEAT COMPARTMENT FITTING ,TRIMMINGS ,GARNISH AND ETC	New	100.00	0.00
Gross Labour Cost (S\$)			2,510.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >