

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21010060/GVF3N2**Date:** 12/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000074
Claimant Vehicle No :	SHD3320R	Insured Vehicle No :	SLK1358L
Date of Loss:	27/09/2021	Nature of Claim:	TP
		Claim No:	M2104534

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3320R		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS043946
Reg. Date:	25/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FUX03557236
Colour:	Blue	Odometer:	653265 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	499.17	124.25	374.92	75.11
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	700.00	600.00	100.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,210.17	735.25	474.92	39.24
Approved Total (Overridden) (S\$)		600.00		
(S\$)	1,210.17	600.00	610.17	50.42
+ GST 7.00/7.00% (S\$)	84.71	42.00	42.71	50.42
Nett Amount (S\$)	1,294.88	642.00	652.88	50.42

INSPECTION

Date of Assignment:	28/09/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/09/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2021)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3320R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Repair	499.90 FL	-	*- FL
2	1		*FRT NUMBER PLATE	Bent	50.00 F	-	*50.00 FS
3	1		*FRT NUMBER PLATE MOULDING	Deformed	99.00 FL	-	*99.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (S\$)	648.90	149.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	149.73	24.75
					Total Parts (S\$)	499.17	124.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	TOWING	New	-	0.00
Gross Labour Cost (\$\$)			700.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >