#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010061/UTCE2

29/12/2021 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00032092100

**Claimant Vehicle** 

FBH2252K

Insured

GX2627U

No: Date of Loss: 21/09/2021

Vehicle No:

Nature of Claim: TP

SNM21D205504/C02/TOHHS

RC70E5004187

86709 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

FBH2252K Reg No:

Make & Model: HONDA NC750XA, 745cc Reg. Date: 01/01/2014 (Man. Year: 2014)

Chassis No: Odometer:

Engine No:

JH2RC72B4EK002486

Yes

Colour:

Black

**Engine Capacity:** 745 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 160/60Z R17 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: Rear Right Side:  $0 \, \text{mm}$ 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,371.00	746.90	1,624.10	68.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	653.00	380.00	273.00	41.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,024.00	1,126.90	1,897.10	62.73
Approved Total (Overridden) (S\$)		900.00		
(S\$)	3,024.00	900.00	2,124.00	70.24
+ GST 7.00/7.00% (S\$)	211.68	63.00	148.68	70.24
Nett Amount (S\$)	3,235.68	963.00	2,272.68	70.24

**INSPECTION** 

Date of Assignment: 28/09/2021

Ban Hock Hin Co. Pte Ltd (HQ) Date Inspected: 29/09/2021 Inspected At:

No. 6 Defu Lane 4 Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

## **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 29 Dec 2021)

Parts: N/A HONDA NC750XA 745cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBH2252K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ARM MAIN STEP LH FOOTREST	Cut	98.00 F	*98.00 FL
2	1		*BOLT FOOTREST	Cut	8.00 F	*8.00 FL
3	1		*BOX REAR (KAPPA) K-VENTURE 58L	Serviceable	930.00 F	*-FL
4	1		*BOX TOOLS	Broken	91.00 F	*91.00 FL
5	1		*SET CRASH BAR	Damaged	330.00 FS	*80.00 FS
6	1		*FOOTREST REAR LH	Cut	60.00 F	*60.00 FL
7	1		*GUARD HANDLE BAR	Cut	91.00 F	*91.00 FL
8	1		*MIRROR LH	Cut	148.00 F	*148.00 FL
9	1		*MUDGUARD FRONT	Repair	364.00 F	*-FL
10	1		*PEDAL BRAKE	Bent	142.00 F	*142.00 FL
11	1		*PROTECTOR MUFFLER	Bent	103.00 F	*103.00 FL
12	1		*RUBBER GEAR PEDAL	Not Necessary	6.00 F	*- FL
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,371.00	821.00
			- List Item Discount o	on L Items 0.00/10.00% (S\$)	0.00	74.10
				Total Parts (S\$)	2,371.00	746.90
				_		

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	DIAGNOSTIC (ECU/ABS/FI)	New	91.00	80.00
2	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	378.00	300.00
3	PEDAL CHANGE COMP	New	184.00	0.00
		Gross Labour Cost (S\$)	653.00	380.00
	Report was unsubmi	tted during this print-out.		

< END OF ESTIMATES >