

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010063/APA3Q2**Date:** 23/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0002723_02

Claimant Vehicle No : SJK8827C **Insured Vehicle No :** SMA5637X

Date of Loss: 26/09/2021 Nature of Claim: TP Claim No: MPC2021D0004209

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK8827C**
 Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A1794114
 Reg. Date: 07/11/2008 (Man. Year: 2008) Chassis No: RN61084875
 Colour: Black Odometer: 167959 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,256.30	16,978.00	10,278.30	37.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,230.00	3,150.00	3,080.00	49.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,486.30	20,128.00	13,358.30	39.89
Approved Total (Overridden) (S\$)		15,800.00		
Nett Amount (S\$)	33,486.30	15,800.00	17,686.30	52.82
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		17,096.45		

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 29/09/2021 Inspected At: Kt Motorwerk (HQ)
Blk 3012 Bedok Industrial Park E, #01-202
Singapore 489978

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8827C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
2	1		*FRONT BUMPER	Distorted	685.60 F	*685.60 FL
3	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
4	2		*FRONT BUMPER SIDE HOLDER	Damaged	49.00 F	*49.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Distorted	123.50 F	*123.50 FL
6	2		*FRONT BUMPER SIDE GRILLE	Not Necessary	134.20 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	245.60 F	*245.60 FL
8	1		*FRONT BUMPER COVER SPOILER	Smashed	1,000.00 FS	*700.00 FS
9	1		*FRONT GRILLE	Smashed	480.00 FS	*350.00 FS
10	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
11	2		*HEADLAMP	Cracked	1,360.80 F	*1,360.80 FL
12	2		*HEADLAMP LOWER BRACKET	Cracked	131.80 F	*131.80 FL
13	1		*BONNET	Buckled	686.90 F	*686.90 FL
14	1		*BONNET LOCK	Damaged	85.10 F	*85.10 FL
15	2		*BONNET HINGE	Bent	90.40 F	*90.40 FL
16	1		*BONNET INSULATOR	Not Necessary	110.20 F	*- FL
17	1		*BONNET INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
18	1		*BONNET WEATHERSTRIPE	Not Necessary	48.50 F	*- FL
19	1		*BONNET WEATHERSTRIPE CLIPS	Not Necessary	20.00 FS	*- FS
20	1		*FRONT SUPPORT PANEL	Distorted	628.40 F	*628.40 FL
21	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	125.40 F	*125.40 FL
22	1		*FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	20.00 FS	*20.00 FS
23	1		*AIR CON CONDENSER	Distorted	826.40 F	*826.40 FL
24	2		*AIR CON CONDENSER TOP MOUNTING	Damaged	52.00 F	*52.00 FL
25	2		*AIR CON CONDENSER LOWER MOUNTING	Not Necessary	56.00 F	*- FL
26	1		*AIR CON DISCHARGE PIPE	Bent	264.90 F	*264.90 FL
27	1		*AIR CON SUCTION PIPE	Bent	282.30 F	*282.30 FL
28	1		*AIR CON LIQUID PIPE	Bent	195.40 F	*195.40 FL
29	1		*AIR CON FAN COWLING	Damaged	85.10 F	*85.10 FL
30	1		*AIR CON FAN BLADE	Not Necessary	68.60 F	*- FL
31	1		*AIR CON FAN MOTOR	Damaged	308.80 F	*308.80 FL
32	1		*RADIATOR	Distorted	1,483.10 F	*1,483.10 FL
33	2		*RADIATOR TOP BRACKET	Bent	58.00 F	*58.00 FL
34	2		*RADIATOR LOWER MOUNTING	Not Necessary	48.00 F	*- FL
35	1		*RADIATOR SPARE TANK	Deformed	68.40 F	*68.40 FL
36	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
37	1		*RADIATOR FAN COWLING	Cracked	109.40 F	*109.40 FL
38	1		*RADIATOR FAN BLADE	Not Necessary	68.40 F	*- FL
39	1		*RADIATOR FAN MOTOR	Damaged	316.00 F	*316.00 FL
40	1		*BATTERY COVER	Deformed	84.10 F	*84.10 FL
41	1		*BATTERY LOWER TRAY	Deformed	65.80 F	*65.80 FL
42	1		*BATTERY	Not Necessary	250.00 FS	*- FS
43	1		*AIR CLEANER HOUSING	Cracked	310.80 F	*310.80 FL
44	1		*AIR CLEANER HOSE	Not Necessary	98.70 F	*- FL
45	1		*FUSE BOX	Not Necessary	455.70 F	*- FL
46	2		*ENGINE MOUNTING	Not Necessary	537.80 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*ENGINE MOUNTING BRACKET	Not Necessary	128.90 F	*- FL
48	2		*FRONT FENDER	Buckled	972.40 F	*972.40 FL
49	2		*FRONT FENDER TOP GARNISH	Deformed	73.00 F	*73.00 FL
50	1		*FRONT FENDER TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
51	2		*FRONT FENDER INNER SHIELD	Not Necessary	284.80 F	*- FL
52	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
53	1		*ENGINE UNDERCOVER	Torn	159.60 F	*159.60 FL
54	1		*ENGINE UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
55	1		*ROCKER PANEL OUTER SKIRTING LH	Cracked	680.00 FS	*500.00 FS
56	1		*ROCKER PANEL OUTER SKIRTING CLIPS	Necessary	30.00 FS	*30.00 FS
57	1		*FRONT SUB FRAME	Not Necessary	1,181.70 F	*- FL
58	2		*ROOF SIDE MOULDING	Not Necessary	394.40 F	*- FL
59	1		*ROOF SIDE MOULDING CLIPS	Not Necessary	60.00 FS	*- FS
60	1		*WIPER PANEL GARNISH	Not Necessary	185.60 F	*- FL
61	1		*INTAKE MANIFOLD HEAT SHIELD	Not Necessary	90.10 F	*- FL
62	1		*RADIATOR TOP HOSE	Twisted	45.40 F	*45.40 FL
63	1		*RADIATOR LOWER HOSE	Not Necessary	39.40 F	*- FL
64	1		*ENGINE ECU	Not Necessary	1,431.40 F	*- FL
65	1		*ENGINE ECU COVER	Not Necessary	86.40 F	*- FL
66	2		*AIR BAG SENSOR	Activated	379.80 F	*379.80 FL
67	1		*AIR BAG ECU	Activated	1,308.50 F	*1,308.50 FL
68	2		*SAFETY BELT	Activated	1,388.00 F	*1,388.00 FL
69	1		*STEERING WHEEL AIR BAG	Activated	1,890.90 F	*1,890.90 FL
70	1		*STEERING WHEEL ANTI CLOCK SPRING	Activated	325.40 F	*325.40 FL
71	1		*DASHBOARD	Torn	768.80 F	*768.80 FL
72	1		*DASHBOARD AIR BAG	Activated	2,236.80 F	*2,236.80 FL
73	1		*RADIO CONSOLE	Cracked	485.50 F	*485.50 FL
74	1		*AIR RESONATOR	Smashed	240.40 F	*240.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,256.30	20,777.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,799.50
Total Parts (\$\$)	27,256.30	16,978.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING	New	1,800.00	1,000.00
3	WIRING	New	200.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS	New	120.00	60.00
6	TO REMOVE RADIATOR AND TO TOP UP COOLANT	New	120.00	60.00
7	TO DISMANTLE FRONT UNDERCARRIAGE	New	400.00	0.00
8	TO REMOVE SAFETY BELTS	New	250.00	180.00
9	TO REMOVE DASHBOARD	New	350.00	200.00
10	TO REMOVE AIR BAGS AND TO PERFORM DIANOGSTIC TEST	New	480.00	300.00
11	TO REPLACE ENGINE MOUNTINGS	New	300.00	0.00
12	TOWING CHARGES	New	60.00	60.00
Gross Labour Cost (\$\$)			6,230.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >