

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010064/GPS3Q2**Date:** 14/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210032969
Claimant Vehicle No :	SLA4606D	Insured Vehicle No :	SKE9991Z
Date of Loss:	23/09/2021	Nature of Claim:	TP
		Claim No:	5054783299SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA4606D	Engine No:	2ZR1703917
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W40J003777
Reg. Date:	01/03/2016 (Man. Year: 2016)	Odometer:	437170 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/09/2021	
Date Inspected:	29/09/2021	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$55,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT RH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
4	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
5	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
6	1		*FRT RH HEADLAMP ASSY	Scratched	0.00 F	*- F
7	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
8	1		*FRT RH FENDER	Repair	0.00 F	*- F
9	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
10	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
11	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >