

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010066/ETCN2**Date:** 22/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00123382001

**Claimant Vehicle
No :** SKE2903A**Insured Vehicle
No :** GBJ7284A

Date of Loss: 24/09/2021

Nature of Claim: TP

Claim
No: SNM21D205456/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKE2903A**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGJH722112

Reg. Date: 20/03/2019 (Man. Year: 2018)

Chassis No: KNAF3416MK5031127

Colour: Grey

Odometer: 39089 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size:

225/45R17

Front Left Side: Kumho 4 mm

Rear Left Side:

Kumho 4 mm

Front Right Side: Kumho 4 mm

Rear Right Side:

Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,427.00	3,745.00	4,682.00	55.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,860.00	3,990.00	2,870.00	41.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,287.00	7,735.00	7,552.00	49.40
+ GST 7.00/7.00% (S\$)	1,070.09	541.45	528.64	49.40
Nett Amount (S\$)	16,357.09	8,276.45	8,080.64	49.40

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 13/10/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan
Gardens)

209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE2903A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FS	*1,297.00 FS
2	1		*HINGE ASSY-TRUNK LID,LH	Not Necessary	97.00 FS	*- FS
3	1		*HINGE ASSY-TRUNK LID,RH	Not Necessary	97.00 FS	*- FS
4	1		*PANEL ASSY-BACK	Repair	324.00 FS	*- FS
5	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FS	*32.00 FS
6	1		*EMBLEM-CERATO	Cut	28.00 FS	*28.00 FS
7	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 FS	*- FS
8	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FS	*- FS
9	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 FS	*- FS
10	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FS	*- FS
11	1		*COVER-RR BUMPER	Crushed	651.00 FS	*651.00 FS
12	1		*COVER-RR BUMPER LWR	Cut	241.00 FS	*241.00 FS
13	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FS	*- FS
14	1		*BEAM-RR BUMPER	Not Necessary	318.00 FS	*- FS
15	1		*STAY-RR BUMPER LH	Not Necessary	65.00 FS	*- FS
16	1		*STAY-RR BUMPER RH	Not Necessary	65.00 FS	*- FS
17	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Not Necessary	25.00 FS	*- FS
18	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Not Necessary	31.00 FS	*- FS
19	4		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	652.00 FS	*- FS
20	1		*COVER-RR BUMPER FOG LAMP,LH	Cut	88.00 FS	*88.00 FS
21	1		*COVER-RR BUMPER FOG LAMP,RH	Not Necessary	88.00 FS	*- FS
22	1		*LAMP ASSY-SIDE T-SIGNAL,LH	Not Necessary	181.00 FS	*- FS
23	1		*LAMP ASSY-SIDE T-SIGNAL,RH	Not Necessary	181.00 FS	*- FS
24	1		*LAMP ASSY-CENTER GARNISH	Cut	690.00 FS	*690.00 FS
25	1		*LAMP ASSY-REAR COMB INSIDE,LH	Cracked	608.00 FS	*608.00 FS
26	1		*LAMP ASSY-REAR COMB INSIDE,RH	Not Necessary	608.00 FS	*- FS
27	1		*LAMP ASSY-REAR COMB OUTSIDE,LH	Not Necessary	675.00 FS	*- FS
28	1		*LAMP ASSY-REAR COMB OUTSIDE,RH	Not Necessary	675.00 FS	*- FS
29	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
30	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
31	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,427.00	3,745.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER,RR END PNL & BOOTLID	New	3,200.00	1,280.00
2	RESPRAY RR BUMPER,RR END PNL & BOOTLID	New	1,650.00	1,100.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	300.00	200.00
4	REMOVE & REFIT RR FLR BOARD,TRIM & CARPET	New	300.00	200.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
6	SUPPLY RR NUMBER PLATE WITH CASING	New	80.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
8	REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
10	REPAIR REAR END PANEL	New	400.00	400.00
11	SPRAY PAINT REAR END PANEL	New	350.00	350.00
Gross Labour Cost (\$\$)			6,860.00	3,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >