

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010067/ETCE2

Date: 28/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00043882102
Claimant Vehicle No: SLS5772E Insured Vehicle No: GBH3366J
Date of Loss: 25/09/2021 Nature of Claim: TP Claim No: SNM21D205454/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS5772E
Make & Model: SKODA KODIAQ, 1.4 (A) Engine No: CZP161054
Reg. Date: 16/10/2018 (Man. Year: 2018) Chassis No: TMBMD9NSXJ8098283
Colour: Blue Odometer: 53107 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19 Rear Tyre Size: 245/45 R19
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,020.89	7,328.64	3,692.25	33.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,110.00	7,090.00	7,020.00	49.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,130.89	14,418.64	10,712.25	42.63
+ GST 7.00/7.00% (S\$)	1,759.16	1,009.30	749.86	42.63
Nett Amount (S\$)	26,890.05	15,427.94	11,462.11	42.63

INSPECTION

Date of Assignment: 28/09/2021
Date Inspected: 30/09/2021 Inspected At: Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2021)
Parts:	M1-SUV	SKODA KODIAQ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5772E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Dented	3,903.90 FS	*3,903.90 FS
2	2		*1L WINDOW ADHESIVE	Necessary	102.32 FS	*102.32 FS
3	1		*ALL PURPOSE CLEANER	Necessary	97.37 FS	*97.37 FS
4	1		*PRIMER	Necessary	28.44 FS	*28.44 FS
5	1		*ACTIVATOR FOR PRECOATED W	Necessary	26.15 FS	*26.15 FS
6	2		*APPLICATOR	Necessary	20.88 FS	*20.88 FS
7	1		*HOOD LATCH BOOT LID LOCK	Not Necessary	249.05 FS	*- FS
8	1		*WEBBING ADHESIVE TAPE	Necessary	27.09 FS	*27.09 FS
9	1		*UNBEKANNT SKODA EMBLEM	Necessary	77.55 FS	*77.55 FS
10	1		*INSCRIPTIO NAME PLATE - SKODA	Necessary	73.51 FS	*73.51 FS
11	1		*LETTERING NAME PLATE - KODIAQ	Necessary	99.42 FS	*99.42 FS
12	1		*INSCRIPTIO NAME PLATE - 4X4	Necessary	100.37 FS	*100.37 FS
13	1		*HIGH-MOUNT 3RD BRAKELIGHT	Necessary	182.27 FS	*182.27 FS
14	1		*TAILLIGHT RHS TAILLIGHT OUTER	Not Necessary	759.42 FS	*- FS
15	1		*LED TAIL L RHS TAILLIGHT INNER	Not Necessary	552.60 FS	*- FS
16	2		*BALL SCREW BOLT	Necessary	6.48 FS	*6.48 FS
17	1		*REFLECTOR RH	Not Necessary	39.00 FS	*- FS
18	1		*COVER FOR REAR BUMPER	Dented	1,776.63 FS	*1,776.63 FS
19	1		*COVER FOR REAR BUMPER (LOWER BLACK)	Torn	520.87 FS	*514.49 FS
20	1		*COVER FOR TOWING	Torn	28.57 FS	*28.57 FS
21	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
22	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
23	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
24	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
25	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
26	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
27	1		*SENSOR PRIMED	Not Necessary	178.20 FS	*- FS
28	1		*SEAL RING SATIN BLACK	Necessary	4.33 FS	*4.33 FS
29	1		*BONDING AGENT FOR PLASTIC	Necessary	65.18 FS	*65.18 FS
30	1		*BUMP STRIP	Not Necessary	228.23 FS	*- FS
31	2		*DOUBLE COLLARED STUD	Not Necessary	17.70 FS	*- FS
32	1		*FOAM REINF	Not Necessary	132.06 FS	*- FS
33	1		*RETAINING BUMPER CTR BRACKET	Not Necessary	78.84 FS	*- FS
34	1		*GUIDE PIEC LHS BUMPER BRACKET (UPPER)	Not Necessary	46.98 FS	*- FS
35	1		*GUIDE PIEC RHS BUMPER BRACKET (UPPER)	Not Necessary	46.98 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*GUIDE PIEC LHS BUMPER BRACKET (SIDE)	Not Necessary	46.98 FS	*- FS
37	1		*GUIDE PIEC RHS BUMPER BRACKET (SIDE)	Not Necessary	46.98 FS	*- FS
38	4		*RIVET	Necessary	4.72 FS	*4.72 FS
39	1		*ABDECKUNG RHR FENDER WHEEL ARCH	Not Necessary	183.60 FS	*- FS
40	8		*GROMMET	Not Necessary	13.60 FS	*- FS
41	1		*WHEELHOUSE RHR FENDER LINER	Not Necessary	179.01 FS	*- FS
42	1		*CONTROL UNIT FOR BLIND SP RHS BLIND SPOT CONTROL UNIT	Not Necessary	886.64 FS	*- FS
43	1		*BRACKET RHS BLIND SPOT BRACKET	Broken	28.49 FS	*28.49 FS
44	1		*2K-PLASTIC ADHESIVE	Necessary	81.16 FS	*81.16 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 11,020.89 7,328.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	CHANGE LANE ASSIST SYSTEM CALIBRATION	New	840.00	840.00
4	LABOUR	New	5,040.00	1,680.00
5	SPRAY PAINT	New	4,800.00	2,400.00
6	R&R REAR W/SCREEN	New	840.00	840.00
7	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
8	R&R REAR LUGGAGE TRIM TO REPAIR REAR PANEL	New	840.00	0.00
9	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (S\$)			14,110.00	7,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >