

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010068/KRS3Q2
Date: 29/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900098108
Claimant Vehicle No :	SMA9527D	Insured Vehicle No :	SLL9375D
Date of Loss:	21/09/2021	Nature of Claim:	TP
		Claim No:	6018782030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA9527D		
Make & Model:	HYUNDAI ACCENT, 1.3 (A)	Engine No:	G4LCJU993855
Reg. Date:	25/06/2018 (Man. Year: 2018)	Chassis No:	KMHCU41BT KU431517
Colour:	Metallic Red	Odometer:	39947 km
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 3 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,038.00	360.00	678.00	65.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	400.00	300.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,738.00	760.00	978.00	56.27
Approved Total (Overridden) (S\$)		600.00		

(S\$)	1,738.00	600.00	1,138.00	65.48
+ GST 7.00/7.00% (S\$)	121.66	42.00	79.66	65.48
Nett Amount (S\$)	1,859.66	642.00	1,217.66	65.48
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Medical Costs (S\$)		248.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,072.60		

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 29/09/2021

Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
 Singapore 575643

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	450.00 FL	*450.00 FL
2	1		*REAR BUMPER RETAINER	Serviceable	25.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	385.00 FL	*- FL
4	1		*REVERSE SENSOR	Serviceable	350.00 FS	*- FS
					Sub Total (\$\$)	1,210.00 450.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	172.00 90.00
					Total Parts (\$\$)	1,038.00 360.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	250.00	200.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	450.00	200.00
Gross Labour Cost (\$\$)			700.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >