

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21009316/GQF3E2-1

**Date:** 13/10/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
Claimant Vehicle No : FBR5356Y Insured Vehicle No : SLJ5273B  
Date of Loss: 28/08/2021 Nature of Claim: TP Claim No: MFL2021D0003691

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR5356Y**  
Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS Engine No: G3J1E0541988  
Reg. Date: 30/07/2020 (Man. Year: 2020) Chassis No: MH3SG4620LJ077231  
Colour: Red Odometer: 0 km  
Engine Capacity: 155 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70-14 Rear Tyre Size: 140/70-14  
Front Left Side: MITAS 5 mm Rear Left Side: MITAS 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,117.00	1,910.90	4,206.10	68.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	250.00	370.00	59.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,737.00</b>	<b>2,160.90</b>	<b>4,576.10</b>	<b>67.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,737.00</b>	<b>1,700.00</b>	<b>5,037.00</b>	<b>74.77</b>

### INSPECTION

Date of Assignment: 28/09/2021  
Date Inspected: 06/09/2021 Inspected At: 411 Changi Road  
Estimated Period of Repair: 2.0 days Repairer: A L Motorwerks

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Oct 2021)	
<b>Parts:</b>	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBR5356Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Grazed	227.50 F	*95.00 FL
2	1		*FRONT RHS FENDER	Grazed	286.00 F	*220.00 FL
3	1		*FRONT RHS MIRROR W/BACKET	Grazed	182.00 F	*30.00 FL
4	2		*FRONT STEERING BEARING (UPPER & LOWER)	Serviceable	273.00 F	*- FL
5	1		*FRONT HANDLE BAR	Serviceable	234.00 F	*- FL
6	1		*FRONT BRAKE LEVER	Grazed	110.50 F	*68.00 FL
7	1		*RHS FOOTREST	Grazed	97.50 F	*75.00 FL
8	1		*RHS BODY GARNISH	Cracked	318.50 F	*195.00 FL
9	1		*RHS RADIATOR COVER GARNISH	Grazed	286.00 F	*50.00 FL
10	1		*RHS REAR LOWER GARNISH (BLACK)	Serviceable	299.00 F	*- FL
11	1		*RHS REAR FENDER GARNISH	Grazed	234.00 F	*65.00 FL
12	2		*REAR SIDE LAMP	Bent	247.00 F	*90.00 FL
13	1		*REAR TAIL GARNISH	Distorted	312.00 F	*150.00 FL
14	1		*REAR TAIL MUDGUARD	Grazed	364.00 F	*95.00 FL
15	1		*REAR EXHAUST PIPE ASSY	Bent	1,664.00 F	*423.00 FL
16	1		*REAR EXHAUST PIPE COVER	Grazed	338.00 F	*60.00 FL
17	1		*RHS FRONT FOOTREST BOARD (TOP)	Deformed	195.00 F	*120.00 FL
18	1		*RHS FRONT FOOTREST BOARD (LOWER GARNISH)	Deformed	234.00 F	*175.00 FL
19	1		*REAR NUMBER PLATE	Bent	15.00 FS	*15.00 FS
20	1		*BOLTS / MISC / SEALS (SUNDRIES)	Necessary	30.00 FS	*20.00 FS
21	1		*IU UNIT	Grazed	170.00 FS	*156.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,117.00</b>	<b>2,102.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	191.10
<b>Total Parts (\$\$)</b>	<b>6,117.00</b>	<b>1,910.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND COMPONENTS	New	500.00	250.00
2	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS	New	60.00	0.00
3	TRANSPORT MOTORCYCLE TO WORKSHOP TO REPAIRS	New	60.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>620.00</b>	<b>250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >