

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010070/DNCM4**Date:** 19/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00005342100

**Claimant Vehicle No :** SLG584C **Insured Vehicle No :** SNA1421R

Date of Loss: 24/09/2021 Nature of Claim: TP Claim No: SNM21D205503/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLG584C**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B21600314

Reg. Date: 20/09/2016 (Man. Year: 2016) Chassis No: MRHFC5650GT000221

Colour: Grey Odometer: 142545 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 25,101.44         | 3,742.32          | 21,359.12         | 85.09         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 6,300.00          | 1,250.00          | 5,050.00          | 80.16         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>31,401.44</b>  | <b>4,992.32</b>   | <b>26,409.12</b>  | <b>84.10</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>4,000.00</b>   |                   |               |
| <b>(\$\$)</b>                             | 31,401.44         | 4,000.00          | 27,401.44         | 87.26         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 2,198.10          | 280.00            | 1,918.10          | 87.26         |
| <b>Nett Amount (\$\$)</b>                 | <b>33,599.54</b>  | <b>4,280.00</b>   | <b>29,319.54</b>  | <b>87.26</b>  |

**INSPECTION**

Date of Assignment: 28/09/2021

Date Inspected: 29/09/2021 Inspected At: JWG International Pte Ltd (HQ)  
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK  
AutoPoint  
Singapore 568047

Estimated Period of Repair: 4.0 days

**Adjuster:** BRYAN TANI**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                               |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 19 Jul 2022)                 |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLG584C)                                                                                                                                     |                                                               |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                                                                 | Condition                      | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------------------------------------------------------------|--------------------------------|-------------|--------------|
| 1   | 1   |          | <b>*BONNET</b>                                                                              | Not Necessary                  | 1,480.00 FL | *- FL        |
| 2   | 1   |          | <b>*BONNET INSULATOR</b>                                                                    | Not Necessary                  | 310.00 FL   | *- FL        |
| 3   | 1   |          | <b>*BONNET SEAL</b>                                                                         | Not Necessary                  | 150.00 FL   | *- FL        |
| 4   | 1   |          | <b>*HEAD LAMP LH / RH</b><br>(2PCS) (O/s Mounting Cracked / N/s Not Necessary)              | O/s Mtg Cracked/N/s Not Nec    | 3,960.00 FL | *1,120.60 FL |
| 5   | 1   |          | <b>*HEAD LAMP TOP GARNISH LH /RH</b><br>(2PCS)                                              | O/s Broken / N/s Not Necessary | 188.00 FL   | *94.00 FL    |
| 6   | 1   |          | <b>*HEAD LAMP LOWER BRACKET LH /RH</b><br>(2PCS) (O/s Mounting Cracked / N/s Not Necessary) | O/s Mtg Cracked/N/s Not Nec    | 196.00 FL   | *98.00 FL    |
| 7   | 2   |          | <b>*HEAD LAMP ECU LH / RH</b>                                                               | Not Necessary                  | 2,478.00 FL | *- FL        |
| 8   | 1   |          | <b>*HEAD LAMP WIRE HARNESS</b>                                                              | Not Necessary                  | 980.00 FL   | *- FL        |
| 9   | 1   |          | <b>*FRONT BUMPER</b>                                                                        | Dented                         | 761.00 FL   | *579.90 FL   |
| 10  | 2   |          | <b>*FRONT BUMPER FOG LAMP LH / RH</b>                                                       | Not Necessary                  | 620.00 FL   | *- FL        |
| 11  | 1   |          | <b>*FRONT BUMPER FOG LAMP GARNISH LH /RH</b><br>(2PCS)                                      | N/s Not Necessary / O/s Cut    | 482.00 FL   | *65.80 FL    |
| 12  | 1   |          | <b>*FRONT BUMPER LOWER GRILLE</b>                                                           | Not Necessary                  | 278.00 FL   | *- FL        |
| 13  | 1   |          | <b>*FRONT BUMPER FOG LAMP WIRE HARNESS</b>                                                  | Not Necessary                  | 930.00 FL   | *- FL        |
| 14  | 1   |          | <b>*FRONT BUMPER LOWER LID</b>                                                              | Not Necessary                  | 690.00 FL   | *- FL        |
| 15  | 1   |          | <b>*FRONT BUMPER UNDER COVER</b>                                                            | Not Necessary                  | 410.00 FL   | *- FL        |
| 16  | 2   |          | <b>*FRONT BUMPER SIDE RETAINER LH / RH</b>                                                  | Serviceable                    | 130.00 FL   | *- FL        |
| 17  | 1   |          | <b>*FRONT BUMPER SPONGE</b>                                                                 | Not fitted                     | 223.00 FL   | *- FL        |
| 18  | 1   |          | <b>*FRONT REINFORCEMENT BAR</b>                                                             | Not Necessary                  | 892.00 FL   | *- FL        |
| 19  | 2   |          | <b>*FRONT REINFORCEMENT BAR AIR BAG SENSOR</b>                                              | Not Necessary                  | 602.00 FL   | *- FL        |
| 20  | 1   |          | <b>*FRONT SUPPORT PANEL</b>                                                                 | Bent                           | 1,590.00 FL | *665.20 FL   |
| 21  | 1   |          | <b>*FRONT SUPPORT PANEL TOP GARNISH</b>                                                     | Not Necessary                  | 230.00 FL   | *- FL        |
| 22  | 1   |          | <b>*A/C CONDENSOR</b>                                                                       | Bent                           | 1,394.00 FL | *704.40 FL   |
| 23  | 1   |          | <b>*A/C CONDENSOR DISCHARGE HOSE</b>                                                        | Not Necessary                  | 492.00 FL   | *- FL        |
| 24  | 1   |          | <b>*A/C CONDENSOR SUCTION HOSE</b>                                                          | Not Necessary                  | 892.00 FL   | *- FL        |
| 25  | 1   |          | <b>*RADIATOR ASSY</b>                                                                       | Not Necessary                  | 1,729.00 FL | *- FL        |
| 26  | 1   |          | <b>*RADIATOR FAN COMPLETE</b>                                                               | Not Necessary                  | 1,490.00 FL | *- FL        |
| 27  | 2   |          | <b>*FRONT FENDER LH / RH</b>                                                                | Not Necessary                  | 1,890.20 FL | *- FL        |
| 28  | 2   |          | <b>*FRONT FENDER INNER SHIELD LH / RH</b>                                                   | Not Necessary                  | 284.60 FL   | *- FL        |
| 29  | 1   |          | <b>*FRONT GRILLE</b>                                                                        | Cracked                        | 1,600.00 FS | *400.00 FS   |
| 30  | 1   |          | <b>*FRONT BUMPER DAYTIME RUNNING LIGHTS</b>                                                 | Not Necessary                  | 1,400.00 FS | *- FS        |
| 31  | 1   |          | <b>*FRONT BUMPER LOWER LID</b>                                                              | Cracked                        | 1,000.00 FS | *600.00 FS   |
| 32  | 1   |          | <b>*BONNET INSULATOR CLIPS</b>                                                              | Not Necessary                  | 50.00 FS    | *- FS        |
| 33  | 1   |          | <b>*HEAD LAMP CLIPS</b>                                                                     | Not Necessary                  | 50.00 FS    | *- FS        |
| 34  | 1   |          | <b>*FRONT GRILLE CLIPS</b>                                                                  | Not Necessary                  | 50.00 FS    | *- FS        |
| 35  | 1   |          | <b>*FRONT BUMPER LOWER GRILLE CLIPS</b>                                                     | Not Necessary                  | 50.00 FS    | *- FS        |
| 36  | 1   |          | <b>*COOLANT</b>                                                                             | Not Necessary                  | 100.00 FS   | *- FS        |
| 37  | 1   |          | <b>*FRONT NO. PLATE &amp; GARNISH</b>                                                       | Broken                         | 200.00 FS   | *80.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>30,251.80</b> | <b>4,407.90</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 5,150.36         | 665.58          |
| <b>Total Parts (\$\$)</b>                                  | <b>25,101.44</b> | <b>3,742.32</b> |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. |     |          |             |           |            |        |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                         | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                     |          |                 |                 |
| 1                              | TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS                                       | New      | 300.00          | 0.00            |
| 2                              | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS                                             | New      | 2,400.00        | 600.00          |
| 3                              | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS                                                      | New      | 2,400.00        | 500.00          |
| 4                              | TO TUFF COAT DAMAGED AREAS                                                                          | New      | 300.00          | 0.00            |
| 5                              | TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS                                             | New      | 200.00          | 120.00          |
| 6                              | TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS                                              | New      | 200.00          | 0.00            |
| 7                              | TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS                                                            | New      | 200.00          | 30.00           |
| 8                              | TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS | New      | 300.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                     |          | <b>6,300.00</b> | <b>1,250.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >