

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010071/BQCQ2
Date: 16/03/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00188342000
Claimant Vehicle No :	SKB156T	Insured Vehicle No :	SGY7775L
Date of Loss:	26/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205477/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB156T		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2309734A
Reg. Date:	16/02/2017 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1722462
Colour:	Brown	Odometer:	102926 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,528.13	13,760.57	12,767.56	48.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	3,510.00	2,340.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,378.13	17,270.57	15,107.56	46.66
Approved Total (Overridden) (\$\$)		13,800.00		
	(\$\$)	32,378.13	13,800.00	18,578.13
+ GST 7.00/7.00% (\$\$)	2,266.47	966.00	1,300.47	57.38
Nett Amount (\$\$)	34,644.60	14,766.00	19,878.60	57.38

INSPECTION

Date of Assignment:	09/11/2021	
Date Inspected:	29/09/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	14.0 days	

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2022)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB156T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	717.00 FL	*717.00 FL
2	1	*FRONT BUMPER RH SIDE RETAINER	Necessary	25.00 FL	*25.00 FL
3	1	*FRONT BUMPER RH SIDE RETAINER	Necessary	25.00 FL	*25.00 FL
4	1	*FRONT GRILLE	Not Damaged	498.30 FL	*- FL
5	1	*FRONT GRILLE EMBLEM	Not Damaged	118.60 FL	*- FL
6	1	*RH HEADLAMP ASSY	Broken	3,243.00 FL	*2,850.00 FL
7	1	*RH HEADLAMP LOWER BRACKET	Not Necessary	31.40 FL	*- FL
8	1	*FRONT RH FENDER	Dented	685.00 FL	*622.70 FL
9	1	*FRONT RH FENDER SPLASH SHIELD	Torn	87.50 FL	*87.50 FL
10	1	*FRONT RH FENDER ARCH MOULDING	Missing	540.50 FL	*540.50 FL
11	1	*WIPER TANK	Not Damaged	154.00 FL	*- FL
12	1	*WIPER TANK MOTOR	Not Damaged	93.00 FL	*- FL
13	1	*FRONT RH SPORT RIM	Cut	1,231.90 FL	*500.00 FL
14	1	*FRONT RH LOWER ARM	Dented	240.50 FL	*240.50 FL
15	1	*FRONT RH LOWER ARM BALL JOINT	Not Necessary	59.30 FL	*- FL
16	1	*FRONT RH SHOCK ABSORBER	Dented	547.50 FL	*547.50 FL
17	1	*FRONT RH SHOCK ABSORBER TOP MOUNTING	Bent	99.10 FL	*99.10 FL
18	1	*FRONT RH KNUCKLE ARM	Dented	534.80 FL	*534.80 FL
19	1	*FRONT RH WHEEL BEARING	Jammed	290.00 FL	*215.20 FL
20	1	*FRONT RH STABILIZER BAR RH LINKAGE	Not Damaged	32.30 FL	*- FL
21	1	*FRONT RH TIE ROD END	Not Damaged	112.40 FL	*- FL
22	1	*FRONT RH DRIVE SHAFT	Not Damaged	986.40 FL	*- FL
23	1	*STEERING RACK AND PINION	Not Damaged	1,254.30 FL	*- FL
24	1	*FRONT RH SIDE MIRROR ASSY	Not Damaged	885.90 FL	*- FL
25	1	*FRONT RH SIDE MIRROR COVER	Not Damaged	95.20 FL	*- FL
26	1	*FRONT RH DOOR	Dented	1,281.10 FL	*1,166.00 FL
27	1	*FRONT RH DOOR FRAME BLACK TAPE	Necessary	32.90 FL	*32.90 FL
28	1	*FRONT RH DOOR PROTECTOR	Missing	323.60 FL	*274.00 FL
29	1	*FRONT RH DOOR UPPER HINGE	Bent	58.50 FL	*58.50 FL
30	1	*FRONT RH DOOR LOWER HINGE	Bent	58.50 FL	*58.50 FL
31	1	*FRONT RH DOOR CHECKER	Not Necessary	42.80 FL	*- FL
32	1	*FRONT RH DOOR INNER TRIM BOARD	Broken	1,958.50 FL	*844.40 FL
33	1	*FRONT RH DOOR LOCK	Jammed	182.20 FL	*182.20 FL
34	1	*FRONT RH DOOR LOCK CATCH	Not Damaged	65.70 FL	*- FL
35	1	*FRONT RH DOOR OUTER HANDLE	Not Damaged	171.30 FL	*- FL
36	1	*FRONT RH DOOR OUTER HANDLE INNER BRACKET	Not Necessary	55.90 FL	*- FL
37	1	*FRONT RH DOOR OUTER HANDLE GASKET	Not Necessary	21.00 FL	*- FL
38	1	*FRONT RH DOOR LOCK SIDE COVER	Not Necessary	36.00 FL	*- FL
39	1	*FRONT RH DOOR WEATHERSTRIP	Not Damaged	139.10 FL	*- FL
40	1	*FRONT RH DOOR LOWER WEATHERSTRIP	Not Damaged	76.40 FL	*- FL
41	1	*FRONT RH DOOR RUB CHANNEL	Not Necessary	192.60 FL	*- FL
42	1	*FRONT RH DOOR RUB CHANNEL RUBBER SEAL	Not Necessary	139.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT RH DOOR GLASS REGULATOR GEAT WITH MOTOR	Not Damaged	563.40 FL	*- FL
44	1		*RH ROCKER PANEL GARNISH	No such part	991.30 FL	*- FL
45	1		*REAR RH DOOR	Dented	1,104.80 FL	*1,104.80 FL
46	1		*REAR RH DOOR FRAME BLACK TAPE (FRONT)	Repeated	29.90 FL	*- FL
47	1		*REAR RH DOOR FRAME BLACK TAPE (REAR)	Necessary	29.90 FL	*29.90 FL
48	1		*REAR RH DOOR PROTECTOR	Not Damaged	264.80 FL	*- FL
49	1		*REAR RH DOOR INNER TRIM BOARD	Not Damaged	1,862.20 FL	*- FL
50	1		*REAR RH DOOR OUTER HANDLE GASKET	Not Damaged	23.00 FL	*- FL
51	1		*REAR RH DOOR WEATHERSTRIP	Not Damaged	132.20 FL	*- FL
52	1		*REAR RH DOOR LOWER RUBBER SEAL	Not Damaged	76.00 FL	*- FL
53	1		*REAR RH FENDER	Dented	685.00 FL	*685.00 FL
54	1		*REAR RH FENDER ARCH MOULDING	Broken	540.50 FL	*360.00 FL
55	1		*REAR RH FENDER SPLASH SHIELD	Not Damaged	186.40 FL	*- FL
56	1		*REAR RH FENDER INNER TRIM BOARD	Not Damaged	405.30 FL	*- FL
57	1		*RH TAILLAMP ASSY	Broken	405.30 FL	*323.70 FL
58	1		*REAR BUMPER	Broken	755.40 FL	*755.40 FL
59	1		*REAR BUMPER RH SIDE RETAINER	Necessary	36.70 FL	*36.70 FL
60	1		*REAR BUMPER LH SIDE RETAINER	Necessary	36.70 FL	*36.70 FL
61	1		*REAR RH SPORT RIM (ORIGINAL)	Cut	1,231.90 FL	*500.00 FL
62	1		*REAR AXLE	Bent	1,251.90 FL	*1,251.90 FL
63	1		*REAR RH SHOCK ABSORBER	Not Damaged	178.00 FL	*- FL
64	1		*REAR RH WHEEL BEARING	Jammed	361.90 FL	*361.90 FL
65	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
66	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
67	1		*SET FRONT RH FENDER ARCH MOULDING CLIPS	Necessary	50.00 FS	*20.00 FS
68	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
69	1		*SET FRONT RH DOOR PROTECTOR CLIPS	Not Necessary	70.00 FS	*- FS
70	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
71	1		*SET REAR RH DOOR PROTECTOR CLIPS	Not Necessary	70.00 FS	*- FS
72	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
73	1		*REAR RH FENDER GLASS SEALANT	Necessary	70.00 FS	*20.00 FS
74	1		*REAR RH FENDER GLASS INNER SEAL	Necessary	40.00 FS	*20.00 FS
75	1		*REAR RH FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
76	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
77	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **29,385.70** **15,267.30**

- List Item Discount on L Items 10.00/10.00% (\$\$) 2,857.57 1,506.73

Total Parts (\$\$) **26,528.13** **13,760.57**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGED BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS	New	2,000.00	1,400.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,800.00	1,200.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REPLACE FRONT RH UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	250.00
6	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
7	REMOVE AND REPLACE FRONT RH DOOR INNER COMPONENTS TO ASSIST REPAIR	New	120.00	80.00
8	REMOVE AND REPLACE REAR RH DOOR INNER COMPONENTS TO ASSIT REPAIR	New	120.00	80.00
9	REMOVE AND REPLACE REAR RH FENDER INNER TRIMS ,SEATS ,ROOF LINING ,BOARDS AND GARNISH TO ASSIST REPAIR	New	350.00	80.00
10	REMOVE AND REINSTAKLL REAR RH FENDER GLASS TO ASSIST REPAIR	New	100.00	60.00
11	REMOVE AND REINSTALL FUEL TANK PIPES AND SENSORS TO ASSIST REPAIR	New	180.00	0.00
12	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	300.00
Gross Labour Cost (\$\$)			5,850.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >