

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010072/EVCN2**Date:** 25/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00006242101

Claimant Vehicle No : SGG1988Z **Insured Vehicle No :** GBE6222L

Date of Loss: 26/09/2021 Nature of Claim: TP Claim No: SNM21D205476/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG1988Z**

Make & Model: KIA NIRO HYBRID, 1.6 (A) Engine No: G4LELS637227

Reg. Date: 16/03/2021 (Man. Year: 2019) Chassis No: KNACB81CVL5383245

Colour: White Odometer: 14425 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,883.00	1,578.00	305.00	16.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,650.00	1,510.00	47.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,043.00	3,228.00	1,815.00	35.99
+ GST 7.00/7.00% (S\$)	353.01	225.96	127.05	35.99
Nett Amount (S\$)	5,396.01	3,453.96	1,942.05	35.99

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 30/09/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2021)
Parts:	M1-SUV	KIA NIRO HYBRID 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG1988Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-FRONT DOOR,RH	Dented	1,466.00 FS	*1,466.00 FS
2	1		*MOULDING ASSY-FRONT FRAME,RH	Necessary	48.00 FS	*48.00 FS
3	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	54.00 FS	*- FS
4	1		*MOULDING ASSY-FRT DR W/LINE,RH	Not Necessary	171.00 FS	*- FS
5	1		*TAPE-FR DR BLACK FRAME RR,RH	Necessary	14.00 FS	*14.00 FS
6	1		*SUNDRIES	Necessary	50.00 FS	*10.00 FS
7	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	1,883.00	1,578.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RHF DOOR	New	1,920.00	640.00
2	RESPRAY RHF DOOR	New	600.00	550.00
3	REMOVE & REFIT RHF DOOR COMPONENT	New	300.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	60.00	60.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
Gross Labour Cost (\$\$)			3,160.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >