

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21010075/APA3Q2**Date:** 18/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100457483
<b>Claimant Vehicle No :</b>	SMR8345D	<b>Insured Vehicle No :</b>	SLA9271C
Date of Loss:	27/09/2021	Nature of Claim:	TP
		Claim No:	4167925064SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMR8345D</b>	Engine No:	CYG024727
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G2JN058900
Reg. Date:	21/05/2018 (Man. Year: 2017)	Odometer:	52864 km
Colour:	Brown		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,675.00	457.60	15,217.40	97.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,152.00	1,722.00	3,430.00	66.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,827.00</b>	<b>2,179.60</b>	<b>18,647.40</b>	<b>89.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,457.89	152.57	1,305.32	89.53
<b>Nett Amount (S\$)</b>	<b>22,284.89</b>	<b>2,332.17</b>	<b>19,952.72</b>	<b>89.53</b>
<b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,574.17</b>		

INSPECTION

Date of Assignment:	04/10/2021		
Date Inspected:	04/10/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,268.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	543.00 FS	*- FS
3	1		*FRONT BUMPER ADAPTER LH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER AIR GRILLE LH	Cut	572.00 FS	*457.60 FS
6	1		*FRONT BUMPER AIR GRILLE COVER -LH	Not Necessary	51.00 FS	*- FS
7	1		*FRONT BUMPER WHEEL SPOILER LH	Not Necessary	264.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE PIECE -LH	Not Necessary	38.00 FS	*- FS
9	1		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
10	4		*FRONT PARKING AID SENSOR SEAL RIN	Not Necessary	6.00 FS	*- FS
11	1		*HEADLIGHT MOUNTING -LH	Not Necessary	118.00 FS	*- FS
12	1		*HEADLIGHT -LH	Not Necessary	9,540.00 FS	*- FS
13	1		*HEADLIGHT LEFT CYLINDER -LH	Not Necessary	236.00 FS	*- FS
14	1		*FRONT FENDER STONE GUARD FILM -LH	Not Necessary	121.00 FS	*- FS
15	1		*FRONT BUMPER RADAR SENSOR COVER -LH	Not Necessary	13.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	275.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	73.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>15,675.00      457.60</b>
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT TO REPAIR LHS FRONT FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,152.00</b>	<b>1,722.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >