



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201356

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/03/2022
Reference CC6/CTI21010076/Aes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLD 2656G
Insured Veh. SLV 7794M
Claim No. SNM21D205488/C02
Policy No. DMPCSNW00197242000
Accident Date 25/09/2021
Inspection Date 27/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21010076/Aes3q2 Date: 14/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLV 7794M	Veh. Inspected	SLD 2656G	
Policy No.	DMPCSNW00197242000	Coverage (\$)	0.00	
Claim No.	SNM21D205488/C02	Excess (\$)	0.00	
Assign From		Assign Date	27/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ACR500192964	Colour	BLACK	
Odometer	149319 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	PIRELLI	6 mm	
L/H Front Tyre	225/50 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2021	Inspection Date	27/09/2021	
Survey held at	ADVANCE AUTO GARAGE 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 2656G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REAR NUMBER PLATE LAMP @\$58.00	NOT NECESSARY	116.00	-
1	REAR BUMPER	DISTORTED	782.00	782.00
2	REAR BUMPER SIDE HOLDER @\$96.10	DAMAGED	192.20	192.20
2	REAR BUMPER TOW COVER @\$47.00	N/S MISSING	94.00	47.00
2	REAR BUMPER REFLECTOR @\$67.10	N/S CRACKED	134.20	67.10
1	REAR END PANEL	DISTORTED	653.10	653.10
1	REAR END PANEL TOP GARNISH	DEFORMED	249.10	249.10
1	REAR END PANEL LOWER GARNISH	DEFORMED	126.80	126.80
1	REAR END PANEL ANTENNA SENSOR	DAMAGED	156.90	156.90
2	TAILLAMP @\$327.10	NOT NECESSARY	654.20	-
1	TAILGATE	DISTORTED	1,380.00	1,380.00
1	TAILGATE LOCK	DAMAGED	490.00	490.00
1	TAILGATE WEATHERSTRIPE	CUT	311.70	311.70
1	TAILGATE CENTRE LAMP	NOT NECESSARY	281.20	-
2	TAILGATE SIDE LAMP @\$266.00	CRACKED	532.00	532.00
1	TAILGATE INNER TRIM BOARD	CRACKED	695.00	695.00
2	TAILGATE AUTO DAMPER @\$389.00	DAMAGED	778.00	778.00
2	TAILGATE AUTO DAMPER SENSOR @\$394.00	NOT NECESSARY	788.00	-
1	TAILGATE AUTO LOCK MOTOR	NOT NECESSARY	564.00	-
1	TAILGATE GLASS MOULDING	NECESSARY	118.50	118.50
1	TOYOTA LOGO	NECESSARY	61.90	61.90
1	ESTIMA WORDING	NECESSARY	59.80	59.80
1	AERAS WORDING	NECESSARY	58.90	58.90
2	REAR FENDER INNER TRIM BOARD @\$627.80	DEFORMED	1,255.60	1,255.60
1	FLOOR PANEL SORROUND TRIM	NOT NECESSARY	556.00	-
1	FLOOR PANEL TOP FOLDABLE BOARD	DEFORMED	687.20	687.20
1	REAR EXHAUST PIPE	NOT NECESSARY	1,081.40	-
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	38.90	-
	LESS 25% DISCOUNT		-	-2,175.70
			12,896.60	6,527.10

Report Ref No. CC6/CTI21010076/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	DEFORMED	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR END PANEL GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR FENDER INNER TRIM BOARD CLIPS (SN)	NECESSARY	60.00	60.00
1	FLOOR PANEL SORROUND TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR CAMERA (SN)	DAMAGED	480.00	380.00
			1,200.00	900.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,200.00	900.00
	SPRAY PAINTING.		1,200.00	900.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO REMOVE UPHOLSTERY .		150.00	80.00
	TO SPRAY TUFF COAT.		150.00	60.00
	TO REMOVE TAILGATE GLASS .		180.00	120.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	80.00
	TO REMOVE AUTO TAILGATE DAMPERS.		150.00	50.00
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
			3,580.00	2,320.00
	GRAND TOTAL		17,676.60	9,747.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,800.00
---	--	--	----------

Report Ref No. CC6/CTI21010076/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 2656G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 2656G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

