

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010077/R1PS3Q2
Date: 19/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993623
Claimant Vehicle No :	SHB796G	Insured Vehicle No :	SLZ7111M
Date of Loss:	25/09/2021	Nature of Claim:	TP
		Claim No:	6522001961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB796G		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZR6586472
Reg. Date:	01/04/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U605767683
Colour:	Maroon	Odometer:	527757 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 5 mm	Rear Left Side:	Sailun 5 mm
Front Right Side:	Sailun 5 mm	Rear Right Side:	Sailun 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,253.18	2,140.20	8,112.98	79.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,050.00	2,200.00	67.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,503.18	3,190.20	10,312.98	76.37
Approved Total (Overridden) (S\$)		2,800.00		

Nett Amount (S\$)	13,503.18	2,800.00	10,703.18	79.26
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$107.00/day) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,435.00		

INSPECTION

Date of Assignment: 27/09/2021

Date Inspected: 27/09/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
2	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
3	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Cracked	94.80 F	*71.10 F
4	1		*BUMPER REAR (DISC 25%)	Cracked	458.60 F	*343.95 F
5	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Deformed	118.10 F	*88.58 F
6	1		*BUMPER LIP REAR (DISC 25%)	Deformed	228.90 F	*171.68 F
7	1		*END PANEL (DISC 25%)	Bent	602.10 F	*451.58 F
8	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
9	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
10	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
11	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
12	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
13	1		*SENSOR REVERSE (SN)	Cracked	180.00 F	*180.00 F
14	1		*END PANEL COVER ,DECK TRIM HOLE	Not Necessary	46.10 F	*- F
15	1		*END PANEL COVER ,DECK TRIM ,RR	Not Necessary	121.10 F	*- F
16	1		*BOX ,DECK FLOOR ,RR	Not Necessary	649.70 F	*- F
17	1		*EXHAUST TAIL PIPE	Not Necessary	656.20 F	*- F
18	1		*SUPPORT EXHAUST REAR	Not Necessary	33.60 F	*- F
19	1		*TAILGATE ASY	Not Necessary	1,007.90 F	*- F
20	1		*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*- F
21	1		*EMBLEM REAR	Not Necessary	60.30 F	*- F
22	1		*NAME PLATE (HYBRID)	Not Necessary	51.90 F	*- F
23	1		*NAME PLATE (PRUIS)	Not Necessary	60.80 F	*- F
24	1		*NAME PLATE (TOYOTA)	Not Necessary	51.90 F	*- F
25	1		*FENDER RR/LH	Not Necessary	766.80 F	*- F
26	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
27	1		*STICKER DECAL 65558888	Not Necessary	21.60 F	*- F
28	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
29	1		*TAILGATE LOCK COVER	Not Necessary	15.70 F	*- F
30	1		*TAIL LAMP RH	Not Necessary	557.80 F	*- F
31	1		*TAIL LAMP LH	Not Necessary	548.40 F	*- F
32	1		*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
33	1		*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
34	1		*ANTENNA ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
35	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*BUMPER SEAL ,RR LH	Not Necessary	88.90 F	*- F
37	1		*BUMPER SEAL ,RR RH	Not Necessary	65.70 F	*- F
38	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
39	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Not Necessary	514.50 F	*- F
40	1		*UNDER COVER RR SHIELD	Not Necessary	63.90 F	*- F
41	1		*SPARE TYRE PANEL	Repair	667.70 F	*- F
F=Franchise part.						
Total Parts (S\$)					10,253.18	2,140.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,854.00	400.00
3	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
4	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	60.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	60.00
6	TO REPLACE SUNDRY PARTS	New	100.00	90.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	40.00
8	TO REMOVE & REFIT EXHAUST	New	120.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,250.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >