

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010078/KPA3Q2**Date:** 26/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700017362
Claimant Vehicle No :	SHB7956R	Insured Vehicle No :	SJZ7733S
Date of Loss:	24/09/2021	Nature of Claim:	TP
		Claim No:	4735113439SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7956R		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZR2C47460
Reg. Date:	30/08/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU303083033
Colour:	Metallic Pearl White/Red	Odometer:	193604 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,911.52	3,792.80	3,118.72	45.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	1,140.00	3,050.00	72.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,101.52	4,932.80	6,168.72	55.57
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	27/09/2021		
Date Inspected:	27/09/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Bent	1,300.70 FL	*1,300.70 FL
2	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE ,LH	Serviceable	193.50 FL	*- FL
3	1		*HANDLE ASSY ,FRONT DOOR OUTSIDE ,LH	Serviceable	390.60 FL	*- FL
4	1		*WEATHERSTRIP ,FRONT DOOR ,LH	Serviceable	231.30 FL	*- FL
5	1		*HINGE ASSY ,FRONT DOOR LOWER LH	Repair	110.60 FL	*- FL
6	1		*HINGE ASSY ,FRONT DOOR UPPER LH	Repair	97.50 FL	*- FL
7	1		*TAPE ,BLACK OUT ,NO.1 FRT LH	Necessary	13.30 FL	*13.30 FL
8	1		*TAPE ,BLACK OUT ,NO.2 FRT LH	Necessary	43.50 FL	*43.50 FL
9	1		*TAPE ,BLACK OUT ,NO.3 FRT LH	Necessary	26.30 FL	*26.30 FL
10	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	Serviceable	926.00 FL	*- FL
11	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	Serviceable	238.30 FL	*- FL
12	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Dented / Cut	594.80 FL	*594.80 FL
13	1		*PANEL SUB-ASSY ,QUARTER ,LH	Repair	871.50 FL	*- FL
14	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
15	1		*FENDER SUB-ASSY ,FRONT LH	Bent	977.80 FL	*977.80 FL
16	1		*LINER ,FRONT FENDER ,LH	Serviceable	202.50 FL	*- FL
17	1		*EMBLEM -SIDE PANEL	Necessary	54.60 FL	*54.60 FL
18	1		*FENDER CLIP	Not Necessary	65.00 FS	*- FS
19	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	65.00 FS	*- FS
21	1		*FRT DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
22	1		*TYRE	Serviceable	350.00 FS	*- FS
23	1		*RIM	Dented	1,879.40 FL	*1,879.40 FL
24	1		*SET CLIP ,ROCKER PANEL MOULDING	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,978.70	5,015.40
- List Item Discount on L Items 25.00/25.00% (S\$)	2,067.18	1,222.60
Total Parts (S\$)	6,911.52	3,792.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	400.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	660.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			4,190.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >