

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21010081/EUF3E2**Date:** 22/11/2021**REFERENCE**

Insured/Claimant: GOH HOOI SOCK ENYE (WU HUI SHU)
Date of Loss: 27/09/2021

Policy No: 1700032660
Nature of Claim: OD Claim No: 8971087833SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8931D**
Make & Model: MITSUBISHI LANCER, 1.3 (A)
Reg. Date: 26/07/2017 (Man. Year: 2017)
Colour: Blue
Engine Capacity: 1590 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 4A92CP5076
Chassis No: JMYSRCY1AGU006859
Odometer: 65248 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,815.47	6,219.65	3,595.82	36.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,405.00	8,570.00	5,835.00	40.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,220.47	14,789.65	9,430.82	38.94
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	23,620.47	14,189.65	9,430.82	39.93
+ GST 7.00/7.00% (S\$)	1,653.43	993.28	660.15	39.93
Nett Amount (S\$)	25,273.90	15,182.93	10,090.97	39.93

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 29/09/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 18.0 days

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*HEADLAMP ASSY, LH	Broken	851.00 FL	*851.00 FL
4	1		*HEADLAMP ASSY, RH	Broken	851.00 FL	*851.00 FL
5	1		*TANK, WINDSHIELD WASHER	Broken	91.00 FL	*91.00 FL
6	1		*HORN	Not Necessary	89.00 FL	*- FL
7	1		*CONDENSER ASSY, A/C REFRIGE	Not Necessary	1,140.00 FL	*- FL
8	1		*RADIATOR ASSY	Not Necessary	1,130.00 FL	*- FL
9	1		*SHROUD, COOLING FAN	Not Necessary	259.00 FL	*- FL
10	1		*MOTOR, COOLING FAN (*)	Not Necessary	472.00 FL	*- FL
11	1		*FAN, COOLING	Not Necessary	75.00 FL	*- FL
12	1		*TANK ASSY, RADIATOR COND	Not Necessary	60.00 FL	*- FL
13	1		*BRACKET, ENG FR MOUNTING	Not Necessary	195.00 FL	*- FL
14	1		*BRKT, ENG RR ROLL STOPPER	Not Necessary	114.00 FL	*- FL
15	1		*BRACKET, ROLL STOPPER	Bent	122.00 FL	*122.00 FL
16	1		*BRACKET, T/M MOUNTING	Not Necessary	163.00 FL	*- FL
17	2		*CLIP, FLOOR TRIM	Not Necessary	8.00 FL	*- FL
18	1		*DUCT, A/CLNR INTAKE	Not Necessary	163.00 FL	*- FL
19	2		*BOLT, FUEL TANK	Not Necessary	4.00 FL	*- FL
20	1		*COVER, HEADLAMP SUPT PANEL	Cut	70.00 FL	*70.00 FL
21	1		*BRACKET, FR BUMPER SIDE, LH	Broken	17.00 FL	*17.00 FL
22	1		*BRACKET, FR BUMPER SIDE, RH	Broken	17.00 FL	*17.00 FL
23	1		*COVER, FR BUMPER	Broken	38.00 FL	*38.00 FL
24	1		*COVER, FR BUMPER GRILLE	Missing	5.00 FL	*5.00 FL
25	1		*COVER, FR BUMPER GRILLE	Cut	5.00 FL	*5.00 FL
26	1		*REINFORCEMENT, FR BUMPER	Bent	93.00 FL	*93.00 FL
27	1		*FACE, FR BUMPER	Broken	1,045.00 FL	*1,045.00 FL
28	1		*GARNISH, FR BUMPER, LH	Not Necessary	30.00 FL	*- FL
29	1		*GARNISH, FR BUMPER, RH	Missing	30.00 FL	*30.00 FL
30	1		*GRILLE, RADIATOR	Broken	270.00 FL	*270.00 FL
31	1		*MARK, THREE-DIA	Missing	70.00 FL	*70.00 FL
32	1		*GRILLE, FR BUMPER	Broken	78.00 FL	*78.00 FL
33	10		*CLIP, FR BUMPER	Necessary	30.00 FL	*30.00 FL
34	1		*REINFORCEMENT, FR BUMPER	Bent	531.00 FL	*531.00 FL
35	1		*WEATHERSTRIP, HOOD, FR	Not Necessary	31.00 FL	*- FL
36	1		*WEATHERSTRIP, HOOD	Not Necessary	18.00 FL	*- FL
37	1		*HINGE, HOOD, LH	Bent	64.00 FL	*64.00 FL
38	1		*HINGE, HOOD, RH	Bent	64.00 FL	*64.00 FL
39	1		*INSULATOR, HOOD	Not Necessary	95.00 FL	*- FL
40	1		*LATCH, HOOD	Bent	58.00 FL	*58.00 FL
41	1		*FENDER, FR LH	Dented	622.00 FL	*622.00 FL
42	1		*FENDER, FR RH	Dented	622.00 FL	*622.00 FL
43	1		*BRACKET, FR FENDER, RH	Broken	16.00 FL	*16.00 FL
44	1		*BRACKET, FR FENDER, LH	Not Necessary	16.00 FL	*- FL
45	1		*PANEL, HEADLAMP SUPPORT, LWR	Bent	511.00 FL	*511.00 FL
46	1		*EXTENSION, FR SIDEMEMBER, RH	Not Necessary	41.00 FL	*- FL
47	1		*EXTENSION, FR SIDEMEMBER, LH	Not Necessary	41.00 FL	*- FL
48	1		*PNL, HEADLAMP SUPT, UPR LH	Bent	86.00 FL	*86.00 FL
49	1		*PNL, HEADLAMP SUPT, UPR RH	Bent	86.00 FL	*86.00 FL
50	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	297.00 FL	*297.00 FL
51	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	141.00 FL	*- FL
52	1		*SHIELD, FR FENDER, FR LH	Not Necessary	119.00 FL	*- FL
53	1		*SHIELD, FR FENDER, FR RH	Crushed	119.00 FL	*119.00 FL
54	1		*COVER, FR DECK GARNISH, LH	Not Necessary	23.00 FL	*- FL
55	1		*COEVR, FR DECK, LH	Not Necessary	9.00 FL	*- FL

Report was unsubmitted during this print-out.

11/22/21, 9:47 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*GARNISH, FR FENDER	Not Necessary	130.00 FL	*- FL
57	1		*HOOD (Supplementary)	Dented	918.00 FL	*918.00 FL
58	1		*GROMMET, HEADLAMP (Supplementary)	Missing	3.00 FL	*3.00 FL
59	1		*CLIPS (Supplementary)	Necessary	3.00 FL	*3.00 FL
60	1		*MEMBER, FR SUSP, CTR (Supplementary)	Bent	244.00 FL	*244.00 FL
61	1		*SUPPORT, FR BUMPER, RH (Supplementary)	Bent	13.00 FL	*13.00 FL
62	2		*CLIPS (Supplementary)	Necessary	8.00 FL	*8.00 FL
63	5		*AT FLUID 1L (Supplementary)	Necessary	77.50 FL	*77.50 FL
64	1		*LLC 4L (Supplementary)	Necessary	26.00 FL	*26.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,717.50	8,071.50
- List Item Discount on L Items 23.00/23.00% (\$\$)					2,902.03	1,851.85
Total Parts (\$\$)					9,815.47	6,219.65
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER, FRT LH BODY CHASSIS & AFFECTED AREA. REPAIR ON FRT RH BODY CHASSIS, FRT LH WHEEL HOUSING	New	6,750.00	2,475.00
2	PAINT WORK ON FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER, BOTH FRT BODY CHASSIS & FRT LH DOOR	New	2,800.00	2,100.00
3	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	REMOVE & INSTALL ENGINE ASSY FOR FACILITATE REPAIR	New	450.00	450.00
6	TO APPLY SEALANT ON AFFECTED AREA	New	150.00	40.00
7	PERFORM RUST PREVENTION	New	160.00	30.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
10	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
11	TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT	New	1,000.00	500.00
12	REPLACE FRONT SUPPORT LOWER, REPAIR BOTH FRONT CHASSIS, BOTH FRONT WHEEL HOUSING (Supplementary)	New	1,575.00	1,575.00
13	RESPRAY ON FRONT SUPPORT LOWER, BOTH FRONT CHASSIS & BOTH FRONT WHEEL HOUSING (Supplementary)	New	1,050.00	1,050.00
Gross Labour Cost (\$)			14,405.00	8,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >