



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 27.09.2021
Emailed : 17.11.2021, 11.10am
Date Survey : 29.09.2021

VEHICLE NO : SLQ 8931 D
MODEL : MIT LANCER EX 1.6
WIP : 15881

Material	:	\$	6,199.65
Labour	:	\$	8,590.00
Sub-Total	:	\$	14,789.65
	:	\$	-
Less Excess	:	\$	600.00
Total	:	\$	14,189.65
GST 7%	:	\$	993.28
Grand Total	:	\$	15,182.93
Finalise By/Date	:	LOI / 17/11/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 30/09/2021	Cust No/Name KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU) Reg No/Reg Date SLQ8931D / 26/07/2017 Date In/Mileage 28/09/2021/ 65248 Chassis/Package JMYSRCY1AGU006859 /DC17S3C Engine No 4A92CP5076 Make/Model MIT/16MY LANCER EX 1.6 (F52) Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/11/2021/ 09:39	BLK	260 / AiTing	15881			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, BOTH FRONT FENDER, & ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN								✓ 2475.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, BOTH FRONT FENDERS, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2100.00
E PNT88000 REMOVE & INSTALL RADIATOR, & A/COND CONDENSER TO FACILITATE REPAIR								✓ 120.00
A 55900099 VACUUM & TOP UP A/COND GAS								✓ 80.00
A 11900199 REMOVE & INSTALL ENGINE ASSY TO FACILITATE REPAIR								? 450.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS								✓ 40.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPLACE FRONT SUPPORT LOWER, REPAIR BOTH FRONT CHASSIS, BOTH FRONT WHEEL HOUSING								1575.00
E PNT98000 RESPRAY ON FRONT SUPPORT LOWER, BOTH FRONT CHASSIS, & BOTH FRONT WHEEL HOUSING								1050.00
E PNT88000 TO MOUNT VEHICLE ON FLOOR BENCH TO CONDUCT CHASSIS ALIGNMENT								? 500.00
X EXC INSURANCE EXCESS								-600.00
X HEADLAMP ASSY,LH					1.00	✓ 851.00	23.00	655.27

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 30/09/2021	Cust No/Name KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU) Reg No/Reg Date SLQ8931D / 26/07/2017 Date In/Mileage 28/09/2021/ 65248 Chassis/Package JMYSRCY1AGU006859 /DC17S3C Engine No 4A92CP5076 Make/Model MIT/16MY LANCER EX 1.6 (F52) Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/11/2021/ 09:39	BLK	260 / AiTing	15881			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	HEADLAMP ASSY,RH				1.00	✓ 851.00	23.00	655.27
X	COVER,HEADLAMP SUPT PANEL				1.00	✓ 70.00	23.00	53.90
X	BRACKET,FR BUMPER SIDE,LH				1.00	✓ 17.00	23.00	13.09
X	BRACKET,FR BUMPER SIDE,RH				1.00	✓ 17.00	23.00	13.09
X	COVER,FR BUMPER				1.00	✓ 38.00	23.00	29.26
X	COVER,FR BUMPER GRILLE				1.00	✓ 5.00	23.00	3.85
X	COVER,FR BUMPER GRILLE				1.00	✓ 5.00	23.00	3.85
X	REINFORCEMENT,FR BUMPER				1.00	✓ 93.00	23.00	71.61
X	FACE,FR BUMPER				1.00	✓ 1045.00	23.00	804.65
X	GARNISH,FR BUMPER,RH				1.00	✓ 30.00	23.00	23.10
X	GRILLE,RADIATOR				1.00	✓ 270.00	23.00	207.90
X	MARK,THREE-DIA				1.00	✓ 70.00	23.00	53.90
X	GRILLE,FR BUMPER				1.00	✓ 78.00	23.00	60.06
X	CLIP,FR BUMPER				10.00	✓ 3.00	23.00	23.10
X	REINFORCEMENT,FR BUMPER				1.00	✓ 531.00	23.00	408.87
X	HINGE,HOOD,LH				1.00	✓ 64.00	23.00	49.28
X	HINGE,HOOD,RH				1.00	✓ 64.00	23.00	49.28
X	FENDER,FR LH				1.00	✓ 622.00	23.00	478.94
X	FENDER,FR RH				1.00	✓ 622.00	23.00	478.94
X	PNL,HEADLAMP SUPT,UPR LH				1.00	✓ 86.00	23.00	66.22
X	PNL,HEADLAMP SUPT,UPR RH				1.00	✓ 86.00	23.00	66.22
X	PANEL,HEADLAMP SUPPORT,UPR				1.00	✓ 297.00	23.00	228.69
X	SHIELD,FR FENDER,FR RH				1.00	✓ 119.00	23.00	91.63
X	HOOD → Supp				1.00	918.00	23.00	706.86
X	LATCH,HOOD				1.00	? 58.00	23.00	44.66
X	BRACKET,FR FENDER,RH				1.00	? 16.00	23.00	12.32
X	GROMMET,HEADLAMP → Supp				1.00	3.00	23.00	2.31
X	TANK,WINDSHIELD WASHER				1.00	? 91.00	23.00	70.07
X	CLIP,HOOD LOCKING → Supp				1.00	3.00	23.00	2.31
X	PANEL,HEADLAMP SUPPORT,LWR				1.00	? 511.00	23.00	393.47
X	BRACKET,ROLL STOPPER				1.00	? 122.00	23.00	93.94
X	MEMBER,FR SUSP,CTR				1.00	244.00	23.00	187.88
X	SUPPORT,FR BUMPER,RH } Supp				1.00	13.00	23.00	10.01

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 30/09/2021	Cust No/Name KCV17997/GOH HOOI SOCK ENYE (WU HUI SHU) Reg No/Reg Date SLQ8931D / 26/07/2017 Date In/Mileage 28/09/2021/ 65248 Chassis/Package JMYSRCY1AGU006859 /DC17S3C Engine No 4A92CP5076 Make/Model MIT/16MY LANCER EX 1.6 (F52) Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/11/2021/ 09:39	BLK	260 / AiTing	15881			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	CLIP,FLOOR TRIM				2.00	4.00	23.00	6.16
X	AT FLUID 1L				5.00	15.50	23.00	59.67
X	LLC 4L				1.00	26.00	23.00	20.02
Z	TEXT							
AIG OD CLAIM, UIL CLAIM SLL846X								
DOA : 27.09.21								
SURVEYOR STEVE LKK 29.09.21								
POLICY NO : 1700032660-04 REPAIR 10D+8D=18D								
Pro Forma								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	6,199.65	Nett	14,189.65
Labour	8,500.00	7% GST on	993.28
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	15,182.93
Diagnostics Job	0.00		
Sundry/Others	-510.00		
Total(w/o GST)	14,189.65		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO.: AIG

Supplementary Parts For Registration No.: SLQ 8931 D

<u>Materials</u>		<u>Cost (\$)</u>
1	Hood	918.00 / DD
2	Grommet, headlamp	3.00 / MIS
3	Clips	3.00 / neC
4	Member, fr susp, Ctr	244.00 / BT
5	Support, Fr bumper, RH	13.00 / BT
6	Clips (x2)	8.00 / neC
7	AT fluid 1L (x5)	77.50 / neC
8	LLC 4L	26.00 / neC

Total Materials	1,292.50
-----------------	----------

<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front support lower, repair both front chassis, both front wheel housing	1,575.00 /
2	Respray on front support lower, both front chassis, & both front wheel housing	1,050.00 /

Total Labour	2,625.00
--------------	----------

Taxable amount	3,917.50
----------------	----------

7% GST	274.23
--------	--------

Grand total	\$ 4,191.73
--------------------	--------------------

Thank You.

Yours faithfully

LOI AL TING
 SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
 DID : 6568 4556 / 6568 4501
 FAX : 6565 1240 / 6567 5258

DL8931D

15881

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Hand	? / SUPP		- DD	5900A709
2	Bracket, engine FR mounting	? / SUPP		- RT	MN 184371
3	Bracket, FR mounting body side	? / SUPP			MN 184299
4	Bracket, engine roll stopper	? / SUPP			MN 184355
5	Bracket, FR roll stopper	? / SUPP			MN 101572
6	member, FR susp dt	? / SUPP		- RT	5900A094
7	AT oil x 5L	? / SUPP		- RK	See 8/11/21
8	Coolant	? / SUPP		- n	
9	LATEL 11-1000	? / SUPP		- RT	5900A056
10	BRACKET, FR FENDER IRH	? / SUPP		- RT	5220C650
11	GRONMET HEADLAMP	? / SUPP		- MS	MN167828
12	TANK WINDSHIELD WASHER	? / SUPP		- RK	8260A117
13	CLIP, HOOD LOCKING	? / SUPP		- RK	MR523317
14	PANEL HEADLAMP SUPPORT LINK	? / SUPP		- DD	5256B113
15	SUPPORT, FR BPR RH	? / SUPP			6400A852
16	Clips - 2 pcs	? / SUPP			MS 938520 2pc
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	25/10/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

Lancer

~~Atfander~~

Steve-Luk

CAR NO: SLQ 89310

WIP: 15881

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	?	/ SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	✓ Replace FRT Support lower	\$225	?	/ SUPP	✓	
2	✓ Repair Both FRT body chassis	\$900	?	/ SUPP	✓	
3	✓ Repair Both FRT wheel housing	\$450	?	/ SUPP	✓	
4	✓ Floor Pulling FRT chassis	\$500	?	/ SUPP	✓	
5	RX I Engine for repair work	\$450	?	/ SUPP	✓	
6	✓ Painting both FRT chassis	\$700	?	/ SUPP	✓	
7	✓ Painting both FRT wheel housing	\$450	?	/ SUPP	✓	
8	✓ Painting FRT support LWR & jte reinforcement	\$700	?	/ SUPP	✓	
9	Body sealant	\$400	?	/ SUPP	✓	
10	Rust Prevention	\$30	?	/ SUPP	✓	
11	Add # days - Total 18 days		?	/ SUPP	✓	
12	08		?	/ SUPP	✓	
13			?	/ SUPP	✓	
14			?	/ SUPP	✓	
15			?	/ SUPP	✓	
16			?	/ SUPP	✓	
17			?	/ SUPP	✓	
18			?	/ SUPP	✓	
19			?	/ SUPP	✓	
20			?	/ SUPP	✓	

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL:

SURVEYOR: Steve - Lkk

All DTCs

2021.11.07

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	CY1A 2016MY

SLD 8931 D.

⇒ M.U.T. III SE Diagnostic check.
↳ Read & Clear DTC. After

All DTCs

2021.11.07

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MP/IGDI/DIESEL	KOS_WCM_8A880001_08MY		No DTCs	
AT/CVT/A-MT/TC-SST	KOS_WCM_8A880001_08MY		No DTCs	
ABS/ASC/ASTC/WSS	KOS_WCM_8A880001_08MY		No DTCs	
SRS-AIR BAG	KOS_WCM_8A880001_08MY		No DTCs	
Air Conditioner	KOS_WCM_8A880001_08MY		No DTCs	
ETACS	KOS_WCM_8A880001_08MY		No DTCs	
Meter	KOS_WCM_8A880001_08MY		No DTCs	
LIN	KOS_WCM_8A880001_08MY		Non-target System	
KOS/IMMO/Keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY		Non-equipped System or Communication Error	