

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III21010082/ATF3E2**Date:** 09/11/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0003736_01

Claimant Vehicle No : SJR9933K **Insured Vehicle No :** SMN763D

Date of Loss: 25/09/2021 Nature of Claim: TP Claim No: MPC2021D0004206

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR9933K**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520368034

Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0342536

Colour: Red Odometer: 44750 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,687.60	4,156.72	5,530.88	57.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,070.00	2,070.00	65.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,827.60	5,226.72	7,600.88	59.25
Approved Total (Overridden) (S\$)		4,150.00		
Nett Amount (S\$)	12,827.60	4,150.00	8,677.60	67.65

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 29/09/2021 Inspected At:

Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2021)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR9933K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,083.30 F	*1,083.30 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	25.20 F	*25.20 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	466.80 F	*- FL
5	1		*FRONT BUMPER FOG LAMP RH	Cracked	351.30 F	*351.30 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	110.20 F	*110.20 FL
7	1		*FRONT BUMPER SIGNAL LAMP RH	Cracked	165.00 F	*165.00 FL
8	1		*FRONT GRILLE CHROME MOULDING RH	Cracked	185.60 F	*185.60 FL
9	1		*HEADLAMP RH	Cut	2,357.30 F	*2,357.30 FL
10	1		*FRONT SUPPORT PANEL	Not Necessary	469.70 F	*- FL
11	1		*RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
12	1		*FRONT RH FENDER	Distorted	392.90 F	*392.90 FL
13	1		*FRONT RH FENDER BRACKET	Bent	75.90 F	*75.90 FL
14	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	129.30 F	*- FL
15	1		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
16	1		*FRONT RH WHEEL RIM	Not Necessary	1,337.20 F	*- FL
17	1		*FRONT RH LOWER ARM	Not Necessary	484.70 F	*- FL
18	1		*FRONT RH SHOCK ABSORBER	Not Necessary	381.00 F	*- FL
19	1		*FRONT RH KNUCKLE ARM	Not Necessary	384.40 F	*- FL
20	1		*FRONT RH WHEEL HUB C/W BEARING	Not Necessary	435.80 F	*- FL
21	1		*WIPER WASHER TANK	Deformed	169.30 F	*169.30 FL
22	1		*WIPER WASHER TANK MOTOR	Not Necessary	112.30 F	*- FL
23	1		*HEADLAMP WASHER PUMP RH	Cracked	242.40 F	*242.40 FL
24	1		*FRONT BUMPER SENSOR RH	Not Necessary	218.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,687.60	5,188.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,031.68

Total Parts (\$\$)	9,687.60	4,156.72
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	600.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS	New	120.00	0.00
6	TO REMOVE RADIATOR AND TO TOP UP COOLANT	New	120.00	0.00
7	TO REMOVE UNDERCARRIAGE	New	350.00	0.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$)			3,140.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >