

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010084/UUCN2**Date:** 15/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00042012101
<b>Claimant Vehicle No :</b>	SJQ3301D	<b>Insured Vehicle No :</b>	SLX5099P
Date of Loss:	25/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205501/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJQ3301D</b>	Engine No:	3ZZ4885448
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106144509
Reg. Date:	04/05/2009 (Man. Year: 2009)	Odometer:	324664 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,698.32	1,528.86	2,169.46	58.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	980.00	1,620.00	62.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,298.32</b>	<b>2,508.86</b>	<b>3,789.46</b>	<b>60.17</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>6,298.32</b>	<b>2,000.00</b>	<b>4,298.32</b>	<b>68.25</b>

**INSPECTION**

Date of Assignment:	29/09/2021		
Date Inspected:	29/09/2021	Inspected At:	SYNERGY BUILDING KAKI BUKIT #01-44
Estimated Period of Repair:	3.0 days		REPAIRER: TSL AUTO GARAGE

**Adjuster:** MARCUS CHUA**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2021)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJQ3301D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/Torn	648.30 FL	*566.01 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	375.60 FL	*- FL
3	1		*FRONT BUMPER BRACKET RH	Not Necessary	61.80 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	78.60 FL	*62.50 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	175.70 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP RH	Cracked	289.90 FL	*289.90 FL
7	1		*FRONT BUMPER FOG LAMP OUTER GARNISH RH	Twisted	89.90 FL	*89.90 FL
8	1		*FRONT BUMPER FOG LAMP BRACKET RH	No such part	43.60 FL	*- FL
9	1		*FRONT BUMPER LOWER UNDER COVER GARNISH RH	Not Necessary	111.20 FL	*- FL
10	1		*FRONT HEADLAMP RH	Scratched	754.30 FL	*754.30 FL
11	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	89.20 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	1,054.10 FL	*- FL
13	1		*WIPER WASHER TANK	Not Necessary	257.40 FL	*- FL
14	1		*RH FRONT FENDER	Repair	412.30 FL	*- FL
15	1		*RH FRONT FENDER INNER COWLING RH	Torn	169.20 FL	*169.20 FL
16	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
17	1		*FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
18	1		*RH FRONT FENDER INNER COWLING CLIPS	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,851.10</b>	<b>2,011.81</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,152.78	482.95
<b>Total Parts (S\$)</b>	<b>3,698.32</b>	<b>1,528.86</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING	New	1,200.00	480.00
2	LABOUR FOR SPRAY PAINTING	New	1,000.00	480.00
3	TO RUST PROOF/TUFF COAT ON REAR ACCIDENT AREAS	New	300.00	0.00
4	WIRING CHECK	New	100.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,600.00</b>	<b>980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >