

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010087/AEA3Q2**Date:** 05/01/2022REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1700011379 |
| Claimant Vehicle No : | SME7078A | Insured Vehicle No : | SBM78J |
| Date of Loss: | 15/09/2021 | Nature of Claim: | TP |
| | | Claim No: | 8968840683SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------------|-------------|--------------|
| Reg No: | SME7078A | | |
| Make & Model: | TOYOTA PRIUS HYBRID, 1.8 S CVT (A) | Engine No: | 2ZR2A68043 |
| Reg. Date: | 11/10/2018 (Man. Year: 2018) | Chassis No: | ZVW506135141 |
| Colour: | Grey | Odometer: | 207018 km |
| Engine Capacity: | 1797 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Rydanz 6 mm | Rear Left Side: | Rydanz 6 mm |
| Front Right Side: | Rydanz 6 mm | Rear Right Side: | Rydanz 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 9,923.90 | 3,704.50 | 6,219.40 | 62.67 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,430.00 | 630.00 | 1,800.00 | 74.07 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,353.90 | 4,334.50 | 8,019.40 | 64.91 |
| Approved Total (Overridden) (S\$) | | 3,400.00 | | |
| (S\$) | 12,353.90 | 3,400.00 | 8,953.90 | 72.48 |
| + GST 7.00/7.00% (S\$) | 864.77 | 238.00 | 626.77 | 72.48 |
| Nett Amount (S\$) | 13,218.67 | 3,638.00 | 9,580.67 | 72.48 |
| + Loss of Use (4.0 x S\$80.00/day) (S\$) | | 320.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 3,965.45 | | |
| Global Sum Settlement (S\$) | | 3,960.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 28/09/2021 | |
| Date Inspected: | 28/09/2021 Inspected At: | MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BONNET | Repair | 855.30 FL | *- FL |
| 2 | 2 | | *FRONT BONNET HINGE | Bent | 144.60 FL | *144.60 FL |
| 3 | 1 | | *FRONT BONNET LOCK | Not Necessary | 144.30 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER | Deformed | 680.20 FL | *680.20 FL |
| 5 | 2 | | *FRONT BUMPER SIDE RETAINER | Necessary | 124.80 FL | *124.80 FL |
| 6 | 2 | | *FRONT BUMPER INNER SIDE GARNISH | Not Necessary | 261.00 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER LOGO | Necessary | 105.30 FL | *105.30 FL |
| 8 | 1 | | *FRONT BUMPER CENTRE GRILLE | Cracked | 380.20 FL | *380.20 FL |
| 9 | 1 | | *FRONT BUMPER LOWER GRILLE | Deformed | 280.30 FL | *280.30 FL |
| 10 | 2 | | *FRONT BUMPER TOWING COVER | Deformed | 100.00 FL | *100.00 FL |
| 11 | 1 | | *FRONT BUMPER DAY LIGHT | N/S Cracked | 1,510.60 FL | *755.30 FL |
| 12 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 488.70 FL | *- FL |
| 13 | 2 | | *FRONT BUMPER REINFORCEMENT BRACKET | Not Necessary | 540.60 FL | *- FL |
| 14 | 1 | | *FRONT BUMPER REINFORCEMENT SPONGE | Cracked | 120.00 FL | *120.00 FL |
| 15 | 1 | | *FRONT BUMPER NUMBER PLATE HOLDER | Not Necessary | 90.00 FL | *- FL |
| 16 | 1 | | *HEADLAMP | N/S Cracked | 4,310.60 FL | *2,155.30 FL |
| 17 | 2 | | *HEADLAMP MODULE | Not Necessary | 1,060.40 FL | *- FL |
| 18 | 2 | | *HEADLAMP LOWER BRACKET | Not Necessary | 160.00 FL | *- FL |
| 19 | 1 | | *FRONT SUPPORT PANEL | Not Necessary | 1,588.30 FL | *- FL |
| 20 | 1 | | *FRONT SUPPORT PANEL TOP COVER | Not Necessary | 140.00 FL | *- FL |
| 21 | 1 | | *FRONT NUMBER PLATE | Cut | 50.00 FS | *50.00 FS |
| 22 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 23 | 1 | | *SET HEADLAMP CLIPS | Not Necessary | 20.00 FS | *- FS |
| 24 | 1 | | *SET FRONT SUPPORT TOP COVER CLIPS | Not Necessary | 20.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$) | 13,195.20 | 4,916.00 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 3,271.30 | 1,211.50 |
| Total Parts (\$) | 9,923.90 | 3,704.50 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|---------------|
| Labour Items | | | | |
| 1 | PANEL BEATING ,REMOVAL AND REPLACING PARTS | New | 1,000.00 | 300.00 |
| 2 | TO SPRAY PAINT AFFECTED AREA | New | 1,000.00 | 300.00 |
| 3 | TUFF COAT | New | 250.00 | 0.00 |
| 4 | WIRING CHECK | New | 180.00 | 30.00 |
| | | | Gross Labour Cost (\$\$) | 630.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >