

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010088/AGA3Q2**Date:** 17/05/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100463824
Claimant Vehicle No :	YP4959C	Insured Vehicle No :	GBE9294J
Date of Loss:	22/09/2021	Nature of Claim:	TP
		Claim No:	6856387370SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4959C	Engine No:	4JJ12D0870
Make & Model:	ISUZU NMR85UH5A, 3.0 D (M)	Chassis No:	JAANMR85HF7103195
Reg. Date:	28/12/2016 (Man. Year: 2015)	Odometer:	76830 km
Colour:	Blue		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,420.56	1,332.39	3,088.17	69.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	810.00	1,530.00	65.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,760.56	2,142.39	4,618.17	68.31
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	6,760.56	1,700.00	5,060.56	74.85
+ GST 7.00/7.00% (S\$)	473.24	119.00	354.24	74.85
Nett Amount (S\$)	7,233.80	1,819.00	5,414.80	74.85
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		2,139.00		

INSPECTION

Date of Assignment:	28/09/2021	
Date Inspected:	28/09/2021	Inspected At: Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL RH	Deformed	285.90 FL	*285.90 FL
2	1		*HEADLAMP RH	Not Necessary	427.00 FL	*- FL
3	1		*SET HEADLAMP CLIPS	Not Necessary	30.00 FL	*- FL
4	1		*HEADLAMP BOTTOM RUBBER LH	Not Necessary	36.00 FL	*- FL
5	1		*FRONT SIGNAL LAMP RH	Not Necessary	245.30 FL	*- FL
6	1		*SET FRONT SIGNAL LAMP CLIPS	Not Necessary	30.00 FL	*- FL
7	1		*FRONT GRILLE	Not Necessary	421.00 FL	*- FL
8	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FL	*- FL
9	1		*FRONT BUMPER	Not Necessary	596.00 FL	*- FL
10	1		*FRONT BUMPER SIDE BRACKET	Not Necessary	97.00 FL	*- FL
11	1		*FRONT DOOR RH	Dented	987.50 FL	*987.50 FL
12	1		*FRONT DOOR SIGNAL LAMP RH	Not Necessary	109.60 FL	*- FL
13	1		*FRONT DOOR INNER TRIM RH	Not Necessary	598.30 FL	*- FL
14	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	198.60 FL	*- FL
15	2		*FRONT DOOR HINGES RH	Not Necessary	157.80 FL	*- FL
16	1		*FRONT DOOR CHECKER RH	Not Necessary	89.50 FL	*- FL
17	1		*FRONT DOOR LOWER ARCH GARNISH RH	Not Necessary	198.20 FL	*- FL
18	1		*FRONT STEP PANEL GARNISH REFLECTOR RH	Not Necessary	65.30 FL	*- FL
19	1		*FRONT STEP PANEL GARNISH RH	Not Necessary	185.90 FL	*- FL
20	1		*SET FRONT DOOR COMPANY STICKER (CUSTOMIZED)	Necessary	350.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,138.90	1,523.40
- List Item Discount on L Items 15.00/15.00% (\$)	718.34	191.01
Total Parts (\$)	4,420.56	1,332.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	400.00
2	SPRAY PAINTING	New	1,000.00	300.00
3	CHECK WIRING ON HEADLAMP	New	120.00	30.00
4	ANTI RUST	New	100.00	0.00
5	REMOVE AND TRANSFER DOOR MECHANISM	New	120.00	80.00
Gross Labour Cost (\$)			2,340.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >