

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010089/ARS3Q2
Date: 26/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210116917
Claimant Vehicle No :	SKP7017S	Insured Vehicle No :	SMD51C
Date of Loss:	27/09/2021	Nature of Claim:	TP
		Claim No:	8705412761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP7017S		
Make & Model:	BMW 335I, 3.0 (A)	Engine No:	10488049N55B30A
Reg. Date:	09/03/2012 (Man. Year: 2012)	Chassis No:	WBA3A92030F095630
Colour:	White	Odometer:	106573 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/55 R19	Rear Tyre Size:	245/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,232.52	5,754.48	1,478.04	20.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,270.00	970.00	43.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,472.52	7,024.48	2,448.04	25.84
Approved Total (Overridden) (S\$)		5,600.00		

(S\$)	9,472.52	5,600.00	3,872.52	40.88
+ GST 7.00/7.00% (S\$)	663.08	392.00	271.08	40.88
Nett Amount (S\$)	10,135.60	5,992.00	4,143.60	40.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 29/09/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,350.00 FL	*1,350.00 FL
2	1		*FRONT BUMPER TOW COVER	Not Necessary	64.20 FL	*- FL
3	1		*FRONT BUMPER SPRAY NOZZLE RH	Damaged	194.90 FL	*194.90 FL
4	1		*FRONT BUMPER SPRAY NOZZLE COVER RH	Deformed	64.80 FL	*64.80 FL
5	1		*FRONT BUMPER SPRAY NOZZLE WATER HOSE RH	Torn	80.00 FL	*80.00 FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Damaged	46.00 FL	*46.00 FL
7	1		*FRONT BUMPER FOG LAMP RH	Cracked	295.00 FL	*295.00 FL
8	1		*FRONT BUMPER FOG LAMP COVER RH	Cracked	90.40 FL	*90.40 FL
9	1		*FRONT BUMPER AIR DUCT RH	Cracked	64.70 FL	*64.70 FL
10	1		*FRONT BUMPER AIR DUCT SUPPORT RH	Not Necessary	68.00 FL	*- FL
11	1		*HEADLAMP RH	Cracked	2,130.60 FL	*2,130.60 FL
12	1		*HEADLAMP BOTTOM RETAINER RH	Not Necessary	136.00 FL	*- FL
13	1		*FRONT RH FENDER	Repair	850.60 FL	*- FL
14	1		*FRONT RH FENDER INNER COWLING RH	Torn	175.20 FL	*175.20 FL
15	1		*BULB REPLACEMENT COVER RH	Missing	35.60 FL	*35.60 FL
16	1		*INTERCOOLER AIR VENT	Not Necessary	135.60 FL	*- FL
17	1		*FRONT BUMPER -M PERFROMANCE	Distorted	1,650.00 FS	*1,650.00 FS
18	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*SET FRONT FENDER TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,521.60	6,207.20
- List Item Discount on L Items 5.00/10.00% (\$\$)	289.08	452.72
Total Parts (\$\$)	7,232.52	5,754.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT/STRAIGHTEN /REALIGN ACCIDENT AFFECTED AREAS	New	1,000.00	600.00
2	TO RESPRAY ACCIDENT AFFECTED AREAS	New	1,000.00	600.00
3	TO TUFF COAT AFFECTED AREAS	New	120.00	40.00
4	TO CONDUCT WIRING CHECK AND REPAIR	New	60.00	30.00
5	TO CHECK AND REALIGN HEADLAMP AND FOCUS	New	60.00	0.00
Gross Labour Cost (S\$)			2,240.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >