

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21010090/EGA3Q2
Date: 14/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210096144
Claimant Vehicle No :	SJE3562E	Insured Vehicle No :	SLQ2M
Date of Loss:	20/09/2021	Nature of Claim:	TP
		Claim No:	0335587624SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE3562E	Engine No:	3A92UGP0965
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH000949
Reg. Date:	25/01/2018 (Man. Year: 2017)	Odometer:	41180 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,854.40	1,147.20	707.20	38.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	650.00	500.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,004.40	1,797.20	1,207.20	40.18
Approved Total (Overridden) (S\$)		1,450.00		

Nett Amount (S\$)	3,004.40	1,450.00	1,554.40	51.74
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
Nett Liability (S\$)		1,600.00		

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 29/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Sin Hup Lee Service Co. (bukit Merah) (HQ)
 BLK 1005 BUKIT MERAH LANE 2, #01-20
 Singapore 159761

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH	Cut	588.00 FL	*588.00 FL
2	1		*FRONT BUMPER	Dented	768.00 FL	*706.00 FL
3	1		*FOG LAMP COVER	Cut	156.00 FL	*127.00 FL
4	1		*FENDER	Repair	486.00 FL	*- FL
5	1		*FENDER SIDE BRACKET LH	Broken	52.00 FL	*13.00 FL
6	1		*FOG LAMP	Not Necessary	268.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,318.00	1,434.00
- List Item Discount on L Items 20.00/20.00% (\$)	463.60	286.80
Total Parts (\$)	1,854.40	1,147.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR ,REMOVE & REFIX DAMAGED PARTS ,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	600.00	200.00
2	TO SPRAY PAINT WORK ON AFFECTED AREAS	New	550.00	450.00
Gross Labour Cost (S\$)			1,150.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >