

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010091/R1VF3E2

Date: 04/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993662
Claimant Vehicle No : YP5179E Insured Vehicle No : SMN5525S
Date of Loss: 24/09/2021 Nature of Claim: TP Claim No: 3934575014SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP5179E**
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M) Engine No: 4P10B96743
Reg. Date: 29/12/2016 (Man. Year: 2015) Chassis No: FEB21EA20168
Colour: White Odometer: 103431 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7/7 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/09/2021
Date Inspected: 29/09/2021 Inspected At: Ngee Ngee Motor
Block K, No. 22 Pandan Road
Singapore 128240
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$51,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR CRASH BAR	Bent	0.00 F	*- F	
2	1		*REAR END PANEL	Bent	0.00 F	*- F	
3	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F	
4	1		*REAR RH TAILLAMP PANEL	Bent	0.00 F	*- F	
5	1		*TAILGATE	Repair	0.00 F	*- F	
6	1		*REAR RUBBER STOPPER RH	Scratched	0.00 F	*- F	
7	1		*REAR RUBBER STOPPER BRACKET	Bent	0.00 F	*- F	
8	1		*TAILGATE HINGE	Scratched	0.00 F	*- F	
9	1		*REAR SIDEGATE LOCK RH	Bent	0.00 F	*- F	
10	1		*SIDEGATE LOWER PANEL	Repair	0.00 F	*- F	
11	1		*REAR WOODEN PILLAR (SIDE)	Repair	0.00 F	*- F	
12	1		*REAR WOODEN PILLAR (REAR)	Cracked	0.00 F	*- F	
13	2		*HOOK	Bent	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >