

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010093/EGA3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700016319
Claimant Vehicle No :	SMD7212J	Insured Vehicle No :	GBD8411A
Date of Loss:	24/09/2021	Nature of Claim:	TP
		Claim No:	8642983522SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7212J	Engine No:	HIDDEN
Make & Model:	SKODA KODIAQ, 1.4 (A)	Chassis No:	TMBKC7NS7J8097395
Reg. Date:	31/08/2018 (Man. Year: 2018)	Odometer:	38149 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,248.93	7,679.90	569.03	6.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,840.00	6,940.00	2,900.00	29.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,088.93	14,619.90	3,469.03	19.18
+ GST 7.00/7.00% (S\$)	1,266.23	1,023.39	242.84	19.18
Nett Amount (S\$)	19,355.16	15,643.29	3,711.87	19.18
+ Car Rental (8.0 x S\$80.00/day + 7.00% GST) (S\$)		684.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,330.09		

INSPECTION

Date of Assignment:	29/09/2021		
Date Inspected:	04/10/2021	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Dented	3,903.90 FS	*3,903.90 FS
2	2		*1K WINDOW ADHESIVE	Necessary	102.32 FS	*102.32 FS
3	1		*ALL PURPOSE CLEANER	Necessary	97.37 FS	*97.37 FS
4	1		*PRIMER	Necessary	28.44 FS	*28.44 FS
5	1		*ACTIVATOR FOR PRECOATED W	Necessary	26.15 FS	*26.15 FS
6	1		*APPLICATOR	Necessary	10.44 FS	*10.44 FS
7	2		*RIVETTED CAP NUT	Necessary	5.00 FS	*5.00 FS
8	1		*HOOD LATCH BOOT LID LOCK	Not Necessary	249.05 FS	*- FS
9	1		*HIGH -MOUNT 3RD BRAKELIGHT	Necessary	181.71 FS	*181.71 FS
10	1		*SKODA EMBL	Necessary	65.07 FS	*65.07 FS
11	1		*INSCRIPTIO NAME PLATE -SKODA	Necessary	73.51 FS	*73.51 FS
12	1		*LETTERING NAME PLATE -KODIAQ	Necessary	99.42 FS	*99.42 FS
13	1		*COVER FOR REAR BUMPER (UPPER)	Dented	1,776.63 FS	*1,776.63 FS
14	1		*COVER FOR REAR BUMPER (LOWER BLACK)	Cut	520.87 FS	*520.87 FS
15	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
16	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
17	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
18	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
19	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
20	1		*SENSOR BRACKET	Necessary	13.22 FS	*13.22 FS
21	1		*BONDING AGENT FOR PLASTIC	Necessary	65.18 FS	*65.18 FS
22	1		*2K-PLASTIC ADHESIVE	Necessary	81.16 FS	*81.16 FS
23	1		*BUMP STRIP	Cut	228.95 FS	*228.95 FS
24	2		*DOUBLE COLLARED STUD	Necessary	17.70 FS	*17.70 FS
25	1		*FOAM REINF	Not Necessary	132.06 FS	*- FS
26	1		*RETAINING BUMPER CTR BRACKET	Necessary	86.76 FS	*86.76 FS
27	1		*GUIDE PIEC LHR BUMPER BRACKET (UPPER)	Not Necessary	46.98 FS	*- FS
28	1		*GUIDE PIEC RHR BUMPER BRACKET (UPPER)	Not Necessary	46.98 FS	*- FS
29	1		*GUIDE PIEC LHR BUMPER BRACKET (SIDE)	Not Necessary	46.98 FS	*- FS
30	1		*GUIDE PIEC RHR BUMPER BRACKET (SIDE)	Not Necessary	46.98 FS	*- FS
31	1		*REAR WATER LEAK TEST	Necessary	150.00 FS	*150.00 FS
32	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,248.93** **7,679.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	4,200.00	2,520.00
4	SPRAY PAINT	New	3,200.00	2,400.00
5	R&R REAR W/SCREEN	New	840.00	840.00
6	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
Gross Labour Cost (\$)			9,840.00	6,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >