



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107817

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 15/11/2021
Reference CC4/FCI21010095/Ura3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 9080C
Insured Veh. YQ 966C
Claim No. D21002696MFCV/1
Policy No. D-21097582MFCV
Accident Date 24/09/2021
Inspection Date 11/10/2021

Description	Total
Survey Inspection	288.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	288.00
GST (7%)	20.16
Grand Total	308.16

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21010095/Ura3q2	
			Date: 15/11/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 966C	Veh. Inspected	GBK 9080C	
Policy No.	D-21097582MFCV	Coverage (\$)	0.00	
Claim No.	D21002696MFCV/1	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	28/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JTFAT35Y50K216126	Colour	SILVER	
Odometer	41251 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	KENDA	6 mm	
L/H Front Tyre	195 R15	KENDA	6 mm	
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/09/2021	Inspection Date	11/10/2021	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 9080C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	WIPER PANEL	BADLY DENTED	971.45	971.45
8	WIPER PANEL CLIPS @\$12.90	NOT NECESSARY	103.20	-
1	FRONT PANEL	BADLY DENTED	1,218.10	1,194.30
1	DYNA 'EMBLEM'	NECESSARY	121.10	121.10
10	FRONT GRILLE CLIPS @\$12.90	NOT NECESSARY	129.00	-
1	FRONT CORNER PANEL -RH	TO REPAIR SEE LABOUR	671.75	-
2	FRONT CORNER PANEL CLIPS @\$12.90	NOT NECESSARY	25.80	-
1	WING MIRROR BRACKET (N/S)	BENT	685.95	600.10
1	WING MIRROR BRACKET MOTOR (N/S)	SHORTED / DAMAGED	789.10	789.10
1	ROUND MIRROR (N/S)	CUT	145.20	145.20
	LESS 25% DISCOUNT		-1,215.16	-955.31
			3,645.49	2,865.94
<u>SPECIAL NETT ITEMS</u>				
1	STICKER (FRONT) (SN)	NECESSARY	25.00	25.00
			25.00	25.00
<u>LABOUR</u>				
	TO REMOVE & REFIX FRONT WINDSCREEN GLASS .		180.00	100.00
	TO CHECK WIRING .		80.00	20.00
	TO REMOVE & REFIT DASHBOARD FASCIA ,INSTRUMENT MEMBER ,WIRING TO FACILITATE JOB REPAIR.		480.00	250.00
	TO REMOVE & REFIX INTERIOR UPHOLSTERY .	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX AIR COND EVAPORATOR ,VACUUM & RECHARGE GAS .		280.00	100.00
	TOWING .	NOT NECESSARY	100.00	-
	TO REMOVE & REPLACE DAMAGED PARTS ,CUT & WELD FRONT PANEL ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS.INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL -RH .		1,150.00	600.00

Report Ref No. CC4/FCI21010095/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY AFFECTED AREAS .		900.00	500.00
			3,290.00	1,570.00
GRAND TOTAL			6,960.49	4,460.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CC4/FCI21010095/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 9080C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 9080C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

