

ASS. REC. BY:

REF:

CT2/210100P71Kc

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Lian 1st Floor Grotto Road by Amk

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

100%

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 880514 Yr Regn: 06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) WagonMake: Hyundai 130 c.c. 1353Colour: M. Beige A/C: Insured / Std / NI / NASp. Reading: 31859 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TNAH3813VJT025937Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: Read Stone 205/55R16Hankook

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 5 mmL/Bal. 7 mm L/Bal. 5 mmD.O.A. 27/9/21 D.O.I. 29/9/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/10 11:00 AM @ 45000 CASH

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

LIAN HUP SENG MOTOR WORKS (UEN : 5301 0052E)

Blk 5035 Ang Mo Kio Industrial Park 2, #01-345

Singapore 569538.

Tel: 64843683 Fax: 66127495

email: lhsmotorworks@hotmail.com

Not Authorised
 11 Sep 84500/h
 Repair After Repair
 4 days

ESTIMATE

M/S : **China Taiping Insurance (Singapore) Pte Ltd**
 3 Anson Road, #16-00
 Singapore 079909

Veh No. : **SMA8805H**
 Make / Model : **Hyundai I30**
 DOA : **27/9/2021**

TMAH3813VJ1025937

S/No	Particulars	QTY	Amount (SGD)
1	LH SIDE MIRROR → 1676.15	1	\$ CM 620.00 ✓
2	LH SIDE MIRROR COVER	1	\$ D/L 150.00 ✓
3	LH FRONT DOOR → 1723.60	1	\$ R 2550.00 ✓
4	LH FRONT DOOR SEAL	1	\$ R 175.00 X
5	LH FRONT DOOR BLACK TAPE	1	\$ R 90.00 ✓
6	LH FRONT DOOR HANDLER	1	\$ R 180.00 ✓
7	LH FRONT DOOR CHROME MOULDING	1	\$ B 150.00 ✓
8	LH FRONR DOOR WINDOW REGULATOR	1	\$ R 315.00 X
9	LH FRONR DOOR POWER WINDOW MOTOR	1	\$ R 235.00 X
10	LH FRONT DOOR HINGE UPPER	1	\$ R 75.00 X
11	LH FRONT DOOR HINGE LOWER	1	\$ R 75.00 X
12	LH FRONT DOOR CHECKER	1	\$ R 150.00 X
13	LH FRONT DOOR LATCH	1	\$ R 150.00 X
14	LH REAR DOOR → 1819.71	1	\$ R 2400.00 ✓
15	LH REAR DOOR HINGE UPPER	1	\$ R 75.00 X
16	LH REAR DOOR HINGE LOWER	1	\$ R 75.00 X
PARTS TOTAL: \$			5,415.00

TO REMOVE, REFIX AND REPAIR AFFECTED DAMAGED PARTS.

INCLUDING KNOCK OUT, WELD AND STRAIGHTEN THE AFFECTED PARTS \$ 400 1,200.00

TO TRANSFER DOOR COMPARTMENT, WINDOW GALSS, REGULATOR, LOCK, ETC TO NEW DOOR \$ 120 400.00

TO CHECK AND CONNET ALL NECESSARY WIRING \$ 20 100.00

TO PUTTY, CLEAN, SPRAY PAINT AND POLISH \$ 500 1,000.00

LABOUR TOTAL: \$ 2,700.00

TOTAL AMOUNT: \$ 8,115.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: