

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010102/KPA3Q2**Date:** 25/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210045794
Claimant Vehicle No :	GBB5249H	Insured Vehicle No :	GBL1338H
Date of Loss:	28/09/2021	Nature of Claim:	TP
		Claim No:	9651751946SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB5249H		
Make & Model:	FIAT FIORINO, 1.3 MJTD (A)	Engine No:	199A20003053439
Reg. Date:	27/05/2009 (Man. Year: 2009)	Chassis No:	ZFA22500000059447
Colour:	Silver	Odometer:	126369 km
Engine Capacity:	1248 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,263.00	7,585.50	677.50	8.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	2,030.00	340.00	14.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,633.00	9,615.50	1,017.50	9.57
Approved Total (Overridden) (S\$)		7,700.00		
(S\$)	10,633.00	7,700.00	2,933.00	27.58
+ GST 7.00/7.00% (S\$)	744.31	539.00	205.31	27.58
Nett Amount (S\$)	11,377.31	8,239.00	3,138.31	27.58
+ Loss of Use (9.0 x S\$70.00/day) (S\$)		630.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,871.00		

INSPECTION

Date of Assignment:	29/09/2021	
Date Inspected:	30/09/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	750.00 FL	*750.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	480.00 FL	*480.00 FL
3	1		*LH TAILGATE	Bent	1,680.00 FL	*1,680.00 FL
4	1		*TAILGATE EMBLEM (FIORINO)	Necessary	60.00 FL	*60.00 FL
5	1		*TAILGATE OUTER HANDLE	Dented	90.00 FL	*90.00 FL
6	1		*TAILGATE INNER LOCK	Jammed	340.00 FL	*340.00 FL
7	1		*TAILGATE INNER BOARD	Distorted	185.00 FL	*185.00 FL
8	1		*TAILGATE GLASS LH	Shattered	470.00 FL	*470.00 FL
9	1		*TAILGATE GLASS INNER LOCK LH	Jammed	380.00 FL	*380.00 FL
10	1		*TAILGATE GLASS INNER BOARD LH	Repeated	190.00 FL	*- FL
11	1		*TAILGATE INNER RUBBER LH (50%)	Cut	171.00 FS	*95.00 FS
12	1		*REAR WIPER ARM	Broken	125.00 FL	*125.00 FL
13	1		*REAR WIPER ARM CAP	Missing	25.00 FL	*25.00 FL
14	1		*TAILLAMP LH	Serviceable	385.00 FL	*- FL
15	1		*RH TAILGATE	Bent	1,750.00 FL	*1,750.00 FL
16	1		*RH TAILGATE LOGO	Necessary	130.00 FL	*130.00 FL
17	1		*RH TAILGATE EMBLEM (MULTIJET)	Necessary	50.00 FL	*50.00 FL
18	1		*RH TAILGATE GLASS	Shattered	490.00 FL	*490.00 FL
19	1		*RH TAILGATE INNER LOCK	Jammed	370.00 FL	*370.00 FL
20	1		*RH TAILGATE INNER RUBBER (50%)	Cut	189.00 FS	*105.00 FS
21	1		*RH TAILGATE INNER BOARD	Distorted	120.00 FL	*120.00 FL
22	1		*REAR END PANEL OUTER	Bent	400.00 FL	*400.00 FL
23	1		*LH TAILGATE GLASS GUM	Necessary	30.00 FS	*30.00 FS
24	1		*RH TAILGATE GLASS GUM	Necessary	30.00 FS	*30.00 FS
25	1		*STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
26	1		*STICKER -3 PAX	Necessary	10.00 FS	*10.00 FS
27	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,110.00	8,375.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	847.00	789.50
Total Parts (\$\$)	8,263.00	7,585.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX LEFT & RIGHT TAILGATE GLASS	New	160.00	140.00
2	REMOVE & REFIX TAILGATE REAR BUMPER ASSY ,REAR LOCK ASSY ,REAR WIPER ,CUT ,WELD & RENEW REAREND PANEL OUTER ,KNOCK & REPAIR REAR END FLOOR BOARD PANEL ,LH SIDE PANEL CORNAL & REALIGN THE SAME	New	1,000.00	800.00
3	REMOVE & REFIX REAR GARNISH ,TOP ROOF LINING ,CARPET ETC	New	120.00	100.00
4	PUTTY & RESPRAY ON REAR LH SIDE PANEL ,REAR FLOOR BOARD PANEL ,REAR END PANEL ,TAILGATES	New	1,000.00	900.00
5	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (\$\$)			2,370.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >