

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010104/BNCE2

Date: 19/09/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00021122100  
Claimant Vehicle No: SKJ5093R Insured Vehicle No: SMV868T  
Date of Loss: 26/09/2021 Nature of Claim: TP Claim No: SNM21D205481/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKJ5093R  
Make & Model: BMW 316I, 1.6 (A) Engine No: A470J424N13B16A  
Reg. Date: 12/04/2013 (Man. Year: 2013) Chassis No: WBA3A12060J719953  
Colour: Blue Odometer: 130602 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40 R19 Rear Tyre Size: 255/40 R19  
Front Left Side: Altenzo 6 mm Rear Left Side: Altenzo 6 mm  
Front Right Side: Altenzo 6 mm Rear Right Side: Altenzo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,606.10	15,941.30	2,664.80	14.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,540.00	1,860.00	54.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,006.10</b>	<b>17,481.30</b>	<b>4,524.80</b>	<b>20.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>14,000.00</b>		
<b>(S\$)</b>	22,006.10	14,000.00	8,006.10	36.38
<b>+ GST 7.00/7.00% (S\$)</b>	1,540.43	980.00	560.43	36.38
<b>Nett Amount (S\$)</b>	<b>23,546.53</b>	<b>14,980.00</b>	<b>8,566.53</b>	<b>36.38</b>

### INSPECTION

Date of Assignment: 29/09/2021  
Date Inspected: 04/10/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875  
Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
<b>Parts:</b>	143	BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKJ5093R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Bent	1,281.00 FL	*1,281.00 FL
2	1	*BONNET RH HINGE	Not Damaged	81.00 FL	*- FL
3	1	*BONNET LH HINGE	Not Damaged	81.00 FL	*- FL
4	1	*BONNET RH LOCK	Not Damaged	89.00 FL	*- FL
5	1	*BONNET RH LOCK CATCH	Not Damaged	29.00 FL	*- FL
6	1	*BONNET LH LOCK	Not Damaged	89.00 FL	*- FL
7	1	*BONNET LH LOCK CATCH	Not Damaged	32.00 FL	*- FL
8	1	*BONNET INNER INSULATOR	Not Damaged	189.00 FL	*- FL
9	1	*FRONT BUMPER EMBLEM	Not Damaged	89.00 FL	*- FL
10	1	*FRONT BUMPER TOWING COVER	Not Damaged	39.00 FL	*- FL
11	1	*FRONT BUMPER RH SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
12	1	*FRONT BUMPER LH SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
13	1	*FRONT BUMPER RH SIDE BRACKET	No such part	25.00 FL	*- FL
14	1	*FRONT BUMPER LH SIDE BRACKET	No such part	25.00 FL	*- FL
15	1	*FRONT BUMPER REINFORCEMENT	Dented	452.00 FL	*452.00 FL
16	1	*FRONT BUMPER REINFORCEMENT LH BRACKET	Dented	56.00 FL	*56.00 FL
17	1	*FRONT BUMPER REINFORCEMENT RH BRACKET	Dented	56.00 FL	*56.00 FL
18	1	*FRONT BUMPER INNER SPONGE	Broken	75.00 FL	*75.00 FL
19	1	*FRONT BUMPER INNER UPPER RUBBER	Not Damaged	152.00 FL	*- FL
20	1	*FRONT BUMPER LH LOWER DUCT COVER	Broken	164.00 FL	*164.00 FL
21	1	*FRONT BUMPER LOWER BEAM	Broken	136.00 FL	*136.00 FL
22	1	*FRONT BUMPER LOWER BEAM RH BRACKET	Dented	95.00 FL	*70.00 FL
23	1	*FRONT BUMPER LOWER BEAM LH BRACKET	Dented	95.00 FL	*70.00 FL
24	1	*FRONT BUMPER INNER SUPPORT GARNISH	No such part	48.00 FL	*- FL
25	1	*FRONT ENGINE LOWER COVER	Not Damaged	234.00 FL	*- FL
26	1	*FRONT WASHER TANK	Not Damaged	156.00 FL	*- FL
27	1	*LH HEADLAMP ASSY	Broken	2,131.00 FL	*2,131.00 FL
28	1	*LH HEADLAMP NOZZLE WASHER COVER	Cut	38.00 FL	*38.00 FL
29	1	*LH HEADLAMP NOZZLE WASHER	Broken	178.00 FL	*178.00 FL
30	1	*LH HEADLAMP TOP PANEL	Bent	85.00 FL	*85.00 FL
31	1	*LH HEADLAMP TOP BRACKET	Bent	22.00 FL	*22.00 FL
32	1	*LH HEADLAMP HID BULB	Broken	376.00 FL	*220.00 FL
33	1	*LH HEADLAMP HID CONTROL UNIT	Short Circuit	835.00 FL	*666.00 FL
34	1	*RH HEADLAMP ASSY	Broken	2,131.00 FL	*2,131.00 FL
35	1	*FRONT TOP PANEL	No such part	202.00 FL	*- FL
36	1	*FRONT TOP PANEL CENTRE BRACKET	No such part	28.00 FL	*- FL
37	1	*FRONT SUPPORT PANEL	Bent	780.00 FL	*593.50 FL
38	1	*AIRCON CONDENSER	Dented	983.00 FL	*983.00 FL
39	1	*RADIATOR ASSY	Dented	1,010.00 FL	*1,010.00 FL
40	1	*RADIATOR FAN ASST	Broken	1,120.00 FL	*1,085.50 FL
41	1	*INTERCOOLER	Dented	987.00 FL	*987.00 FL
42	1	*SET BONNET INNER INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS
43	1	*FRONT BUMPER (M SERIES SPORT)	Broken	1,800.00 FS	*1,800.00 FS
44	1	*FRONT BUMPER LOWER SPOILER	Broken	1,200.00 FS	*800.00 FS
45	1	*FRONT RH GRILLE (M SERIES SPORT)	Broken	320.00 FS	*320.00 FS
46	1	*FRONT RH GRILLE SURROUND MOULDING (M SERIES SPORT)	Broken	220.00 FS	*220.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LH GRILLE (M SERIES SPORT)	Broken	320.00 FS	*320.00 FS
48	1		*FRONT LH GRILLE SURROUND MOULDING (M SERIES SPORT)	Broken	220.00 FS	*220.00 FS
49	1		*FRONT BUMPER CENTRE LOWER GRILLE (M SERIES SPORT)	Broken	285.00 FS	*285.00 FS
50	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
51	1		*FRONT NUMBER PLATE	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,343.00</b>	<b>16,569.00</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	736.90	627.70

<b>Total Parts (\$\$)</b>	<b>18,606.10</b>	<b>15,941.30</b>
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	600.00
2	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	0.00
3	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
4	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR. TO REFILL AIRCON GAS	New	220.00	120.00
5	REMOVE AND REPLACE RADIATOR ASSY, HOSES AND FAN ASSY TO ASSIST REPAIR. TO REFILL COOLANT	New	200.00	100.00
6	REFOCUS AND ADJUST HEADLAMPS ASSY	New	50.00	0.00
7	RESET AND DIAGNOSE FAULT CODE AFTER REPAIR	New	350.00	120.00
8	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,400.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >