

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21010105/BQCN2**Date:** 28/01/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00021122100

**Claimant Vehicle  
No :** SKH9641T**Insured Vehicle  
No :** SMV868T

Date of Loss: 26/09/2021

Nature of Claim: TP

Claim  
No: SNM21D205481/C03/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKH9641T**

Make &amp; Model: BMW 316I, 1.6 (A)

Reg. Date: 31/01/2013 (Man. Year: 2012)

Colour: Grey

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: B316J362N13B16A

Chassis No: WBA3A12020J719514

Odometer: 104320 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R19

Front Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

*The above values represent the remaining tyre tread depth*

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

225/40R19

Goodyear 6 mm

Goodyear 6 mm

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,013.25	7,231.59	9,781.66	57.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,380.00	1,550.00	52.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,943.25</b>	<b>8,611.59</b>	<b>11,331.66</b>	<b>56.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
<b>(S\$)</b>	19,943.25	4,900.00	15,043.25	75.43
<b>+ GST 7.00/7.00% (S\$)</b>	1,396.03	343.00	1,053.03	75.43
<b>Nett Amount (S\$)</b>	<b>21,339.28</b>	<b>5,243.00</b>	<b>16,096.28</b>	<b>75.43</b>

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 04/10/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 6.0 days

**Adjuster:** Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2022)
<b>Parts:</b>	143	BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKH9641T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP ASSY	Cut	2,131.00 FL	*2,131.00 FL
2	1		*FRONT LH FENDER SPLASH SHIELD	Torn	145.00 FL	*145.00 FL
3	1		*FRONT LH DOOR	Dented	1,258.00 FL	*1,258.00 FL
4	1		*FRONT LH DOOR WEATHERSTRIP	Not Damaged	153.00 FL	*- FL
5	1		*FRONT LH SHOCK ABSORBER	Not Damaged	552.00 FL	*- FL
6	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Not Damaged	255.00 FL	*- FL
7	1		*FRONT LH KNUCKLE ARM	Not Damaged	582.00 FL	*- FL
8	1		*FRONT LH LOWER ARM	Not Damaged	321.00 FL	*- FL
9	1		*FRONT LH CONTROL ARM	Not Damaged	297.00 FL	*- FL
10	1		*FRONT LH WHEEL HUB WITH BEARING	Not Damaged	480.00 FL	*- FL
11	1		*FRONT LH TIE ROD END	Not Damaged	95.00 FL	*- FL
12	1		*FRONT CROSSMEMBER	Not Damaged	1,435.00 FL	*- FL
13	1		*STEERING RACK AND PINION	Not Damaged	2,331.00 FL	*- FL
14	1		*FRONT BUMPER (M SERIES SPORT)	Cut	1,800.00 FS	*1,365.39 FS
15	1		*FRONT BUMPER LOWER SPOILER	Cut	1,200.00 FS	*800.00 FS
16	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
17	1		*FRONT LH FENDER (M SERIES SPORT)	Dented	1,050.00 FS	*1,050.00 FS
18	1		*FRONT LH SPORT RIM (LOCAL REPAIR)	Cut	1,800.00 FS	*200.00 FS
19	1		*FRONT LH TYRE	Not Damaged	450.00 FS	*- FS
20	1		*LH SIDE ROCKER PANEL SPOILER	Broken	950.00 FS	*408.90 FS
21	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS
22	1		*FRONT NUMBER PLATE	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>17,515.00</b>	<b>7,408.29</b>
<b>- List Item Discount on L Items 5.00/5.00% (S\$)</b>	501.75	176.70
<b>Total Parts (S\$)</b>	<b>17,013.25</b>	<b>7,231.59</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	700.00
3	CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	500.00	0.00
6	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	120.00	0.00
7	REMOVE AND REINSTALL FRONT LH DOOR INNER MECHANISM TO NEW DOOR	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,930.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >