

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010108/BVCN2**Date:** 18/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00023212100

**Claimant Vehicle
No :** YP8619H**Insured Vehicle
No :** GY2703C

Date of Loss: 24/09/2021

Nature of Claim: TP

Claim
No: SNM21D205509/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **YP8619H**Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU)
(M)

Engine No: 4P10D12555

Reg. Date: 19/03/2018 (Man. Year: 2017)

Chassis No: FEB21EA25048

Colour: Green

Odometer: 56891 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85R15

Rear Tyre Size: 195/85R15

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,732.35	2,898.32	3,834.03	56.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	900.00	1,560.00	63.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,192.35	3,798.32	5,394.03	58.68
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	9,192.35	3,050.00	6,142.35	66.82
+ GST 7.00/7.00% (S\$)	643.46	213.50	429.96	66.82
Nett Amount (S\$)	9,835.81	3,263.50	6,572.31	66.82

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 01/10/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Oct 2021)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP8619H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,850.30 FL	*1,800.00 FL
2	1		*REAR TAILLAMP RH	Not Damaged	517.40 FL	*- FL
3	1		*REAR TAILLAMP LH	Broken	517.40 FL	*226.25 FL
4	1		*REAR TAILLAMP BRACKET RH	Not Damaged	196.44 FL	*- FL
5	1		*REAR TAILLAMP BRACKET LH	Bent	196.44 FL	*196.44 FL
6	1		*REAR TAILGATE HINGE	Necessary	352.17 FL	*231.70 FL
7	1		*REAR TAILGATE LOWER PANEL	Not Damaged	747.35 FL	*- FL
8	1		*REAR TAILGATE LOWER PANEL NUMBER PLATE BRACKET	Not Damaged	128.96 FL	*- FL
9	1		*REAR TAILGATE LOWER PANEL NUMBER PLATE LAMP	Not Damaged	62.70 FL	*- FL
10	1		*REAR TAILGATE LOWER PANEL STEP BRACKET	Not Damaged	479.30 FL	*- FL
11	1		*REAR TAILGATE OUTER LOCK HANDLE LH	Jammed	221.52 FL	*221.52 FL
12	1		*REAR TAILGATE OUTER LOCK HANDLE RH	Not Damaged	221.52 FL	*- FL
13	1		*REAR TAILGATE 60KM/H STICKER	Necessary	40.00 FS	*10.00 FS
14	1		*REAR NUMBER PLATE	Not Damaged	50.00 FS	*- FS
15	1		*REAR REINFORCEMENT BAR	Bent	800.00 FS	*480.00 FS
					Sub Total (S\$)	7,381.50 3,165.91
					- List Item Discount on L Items 10.00/10.00% (S\$)	649.15 267.59
					Total Parts (S\$)	6,732.35 2,898.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	TRANSFER PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	100.00
3	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	400.00
5	APPLY ANTI RUST ON AFFECTED AREA	New	200.00	0.00
Gross Labour Cost (\$)			2,460.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >