

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG121010112/AUF3N2**Date:** 19/11/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SBV2231Y**Insured Vehicle No :** GBA4355X

Date of Loss: 27/09/2021

Nature of Claim: TP

Claim No: CDMCG21001900

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBV2231Y**

Make &amp; Model: HONDA AIRWAVE, 1.5 (A)

Engine No: L15A5120258

Reg. Date: 13/03/2007 (Man. Year: 2006)

Chassis No: GJ11116538

Colour: Grey

Odometer: 183354 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15

Rear Tyre Size:

185/65R15

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,509.00	2,936.80	4,572.20	60.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,510.00	1,250.00	45.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,269.00</b>	<b>4,446.80</b>	<b>5,822.20</b>	<b>56.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,269.00</b>	<b>2,700.00</b>	<b>7,569.00</b>	<b>73.71</b>

INSPECTION

Date of Assignment: 29/09/2021

Date Inspected: 30/09/2021 Inspected At:

BEST SOLUTION AUTOCARE PTE LTD  
53 UBI AVE 1 #03-01  
PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2021)
<b>Parts:</b>	M1-MPV	HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBV2231Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S REAR FENDER	Repair	1,125.00 F	*- FL
2	1		*REAR BUMPER	Deformed	1,088.00 F	*1,088.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	70.00 F	*70.00 FL
4	1		*SET REAR BUMPER CLIP	Necessary	30.00 F	*30.00 FL
5	1		*N/S REAR TAILGATE REFLECTOR	Cracked	295.00 F	*295.00 FL
6	1		*N/S TAIL LAMP	Cracked	312.00 F	*312.00 FL
7	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	398.00 F	*- FL
8	1		*REAR BUMPER INNER SPONGE	Not Necessary	185.00 F	*- FL
9	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	200.00 F	*200.00 FL
10	1		*REAR END PANEL	Repair	625.00 F	*- FL
11	1		*REAR TAILGATE	Dented	1,665.00 F	*1,141.00 FL
12	1		*TAILGATE CHROME GARNISH	Not Necessary	388.00 F	*- FL
13	1		*TAILGATE GLASS SEALANT	Necessary	80.00 F	*80.00 FL
14	1		*TAILGATE WEATHERSTRIP	Not Necessary	235.00 F	*- FL
15	1		*TAILGATE OUTER GARNISH	Deformed	455.00 F	*455.00 FL
16	1		*TAILGATE INNER TRIM BOARD	Not Necessary	358.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,509.00</b>	<b>3,671.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	734.20
<b>Total Parts (\$\$)</b>	<b>7,509.00</b>	<b>2,936.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE DAMAGED PARTS,PANEL BEAT,REPAIR	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
3	ANTI RUST	New	80.00	50.00
4	CHECK WHEEL ALIGNMENT	New	150.00	0.00
5	ELECTRICAL WIRING CHECK	New	80.00	30.00
6	UNDERCARRIAGE	New	120.00	0.00
7	R&R TAILGATE GLASS	New	150.00	120.00
8	R&R CUSHION SEAT CARPET	New	100.00	60.00
9	R&R REVERSE SENSOR	New	80.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>2,760.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >