

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010113/EGA3Q2
Date: 01/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210034677	
Claimant Vehicle No :	SLN1702K	Insured Vehicle No :	GBG6874U	
Date of Loss:	28/09/2021	Nature of Claim:	TP	Claim No: 0674897964SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1702K		
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI (A)	Engine No:	CJS178666
Reg. Date:	25/04/2017 (Man. Year: 2016)	Chassis No:	WWVZZZ3CZHE055321
Colour:	Brown	Odometer:	81522 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,425.94	3,513.13	3,912.81	52.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,420.00	4,140.00	3,280.00	44.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,845.94	7,653.13	7,192.81	48.45
+ GST 7.00/7.00% (S\$)	1,039.22	535.72	503.50	48.45

Nett Amount (S\$)	15,885.16	8,188.85	7,696.31	48.45
+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,704.45		

INSPECTION

Date of Assignment: 01/10/2021

Date Inspected: 01/10/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Broken	1,675.01 FS	*1,675.01 FS
2	1		*SPOILER SATIN BLACK	Not Necessary	259.96 FS	*- FS
3	1		*GUIDE PIECE BUMPER CTR BRACKET	Not Necessary	93.24 FS	*- FS
4	1		*GUIDE PIECE BUMPER INNER BRACKET RH	Not Necessary	34.22 FS	*- FS
5	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Broken	43.45 FS	*43.45 FS
6	1		*FOAM INSERT	Not Necessary	116.84 FS	*- FS
7	1		*SET SENSOR BRACKETS	Necessary	45.72 FS	*45.72 FS
8	1		*2K-PLASTIC ADHESIVE	Necessary	81.16 FS	*81.16 FS
9	1		*BONDING AGENT FOR PLASTIC	Necessary	65.18 FS	*65.18 FS
10	1		*RADIATOR GRILLE SATIN BLA	Broken	605.50 FS	*605.50 FS
11	1		*VENT GRILLE WITH SATIN BL BUMPER CTR BRACKET	Not Necessary	219.22 FS	*- FS
12	1		*COOLING AIR GRILL SATIN B RHS FOG LAMP GRILLE	Not Necessary	108.71 FS	*- FS
13	1		*DECORATIVE MOULDING BRIGHT RHS BUMPER LOWER MLDG CHROM	Not Necessary	92.85 FS	*- FS
14	1		*LED HEADLIGHT RHS LED H/LAMP	Not Necessary	2,472.01 FS	*- FS
15	1		*GASKET	Not Necessary	11.45 FS	*- FS
16	1		*TRIM COVER RHS H/LAMP TOP CHROM	Not Necessary	37.91 FS	*- FS
17	1		*HALOGEN FOG LIGHTS WITH S RHS FOG LAMP	Not Necessary	330.64 FS	*- FS
18	1		*FENDER	Dented	755.26 FS	*755.26 FS
19	1		*BRACKET RHS FENDER BRACKET	Necessary	59.75 FS	*59.75 FS
20	1		*WHEELHOUSE LINER RHS FENDER LINER (UPPER)	Torn	182.10 FS	*182.10 FS
21	1		*RADHAUSSCHALE -KUNSTSTOFF RHS FENDER LINER (LOWER)	Not Necessary	135.76 FS	*- FS
					Total Parts (\$\$)	7,425.94
						3,513.13

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	LABOUR	New	3,360.00	1,680.00
5	SPRAY PAINTI	New	3,200.00	1,600.00
Gross Labour Cost (S\$)			7,420.00	4,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >