

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010115/KPA3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700049490
Claimant Vehicle No :	SMP7146D	Insured Vehicle No :	SLN3770A
Date of Loss:	26/09/2021	Nature of Claim:	TP
		Claim No:	5365789698SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7146D		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Standard (A)	Engine No:	1ZR0E03378
Reg. Date:	11/10/2019 (Man. Year: 2019)	Chassis No:	MR053REH604598821
Colour:	Metallic Silver	Odometer:	121292 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Grenlander 8 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Grenlander 8 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,216.50	5,838.83	3,377.67	36.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	2,270.00	4,230.00	65.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,716.50	8,108.83	7,607.67	48.41
+ GST 7.00/7.00% (S\$)	1,100.16	567.62	532.54	48.41
Nett Amount (S\$)	16,816.66	8,676.45	8,140.21	48.41
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/09/2021	
Date Inspected:	28/09/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled / Cut	536.20 FL	*536.20 FL
2	1		*FENDER SUB-ASSY ,FRONT RH	Bent	919.40 FL	*919.40 FL
3	1		*LINER ,FRONT FENDER ,RH	Distorted	211.50 FL	*211.50 FL
4	1		*EMBLEM ,SIDE PANEL ,RH	Necessary	35.90 FL	*35.90 FL
5	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Bent	1,271.60 FL	*1,271.60 FL
6	1		*HANDLE ASSY ,FRONT DOOR ,OUTSIDE RH	Serviceable	74.70 FL	*- FL
7	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,RH	Serviceable	932.80 FL	*- FL
8	1		*WEATHERSTRIP ,FRONT DOOR OPENING TRIM, RH	Serviceable	296.00 FL	*- FL
9	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	112.00 FL	*- FL
10	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	98.20 FL	*- FL
11	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,RH	Serviceable	320.10 FL	*- FL
12	1		*PANEL SUB-ASSY ,REAR DOOR ,RH	Bent	1,260.00 FL	*1,260.00 FL
13	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM RH	Serviceable	264.90 FL	*- FL
14	1		*HINGE ASSY ,REAR DOOR ,LOWER RH	Repair	98.20 FL	*- FL
15	1		*HINGE ASSY ,REAR DOOR ,UPPER RH	Repair	98.20 FL	*- FL
16	1		*PANEL SUB-ASSY ,QUARTER ,RH	Bent	1,160.20 FL	*1,160.20 FL
17	1		*LINER ,REAR WHEEL HOUSE, RH	Serviceable	347.00 FL	*- FL
18	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Repair	182.80 FL	*- FL
19	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Serviceable	1,272.00 FL	*- FL
20	1		*RIM	Dented	2,031.40 FL	*2,031.40 FL
21	1		*FRT FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
22	1		*FRT FENDER CLIP	Not Necessary	65.00 FS	*- FS
23	1		*FRT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
24	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
25	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	*- FS
26	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	*- FS
27	1		*COVER ,FOG LAMP ,LH	Cut	205.57 FL	*205.57 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,148.67	7,746.77
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,932.17	1,907.94
Total Parts (\$\$)	9,216.50	5,838.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	90.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	700.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	1,320.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (S\$)			6,500.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >