

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010117/AQCN2**Date:** 28/01/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00117282000

**Claimant Vehicle
No :** SMA3767S**Insured Vehicle
No :** YP5043M

Date of Loss: 25/09/2021

Nature of Claim: TP

Claim
No: SNM21D205480/C02/CSCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMA3767S**

Make & Model: HONDA CIVIC, 1.6 5AT (A)

Engine No: R16A14003498

Reg. Date: 21/11/2009 (Man. Year: 2008)

Chassis No: JHMFD46209S200941

Colour: White

Odometer: 151769 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,433.12	2,980.48	2,452.64	45.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,070.00	810.00	43.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,313.12	4,050.48	3,262.64	44.61
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	7,313.12	3,200.00	4,113.12	56.24
+ GST 7.00/7.00% (\$\$)	511.92	224.00	287.92	56.24
Nett Amount (\$\$)	7,825.04	3,424.00	4,401.04	56.24

INSPECTION

Date of Assignment: 01/10/2021

Date Inspected: 29/09/2021 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2022)
Parts:	143	HONDA CIVIC 1.6 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA3767S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	873.90 FL	*683.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	309.50 FL	*309.50 FL
3	1		*FRONT BUMPER RH FOGLAMP GARNISH	Not Necessary	40.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER L/R	O/s Damaged	36.00 FL	*18.00 FL
5	1		*FRONT CHASSIS SIDE MEMBER RH	Repair	450.00 FL	*- FL
6	1		*FRONT HEADLAMP L/R	O/s Cut	2,200.00 FL	*1,100.00 FL
7	1		*FRONT HEADLAMP LOWER BRACKET L/R	O/s Bent	55.00 FL	*27.50 FL
8	1		*FRONT RH FENDER	Dented	606.80 FL	*537.00 FL
9	1		*FRONT RH FENDER INNER BRACKET	Repair	18.00 FL	*- FL
10	1		*FRONT RH FENDER INNER PANEL	Repair	121.60 FL	*- FL
11	1		*FRONT RH FENDER INNER SHIELD	Torn	127.60 FL	*127.60 FL
12	1		*FRONT WASHER TANK	Deformed	98.00 FL	*98.00 FL
13	1		*FRONT WASHER TANK MOTOR	Not Necessary	105.00 FL	*- FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*FRONT BUMPER LOWER SPOILER	Cut	800.00 FS	*600.00 FS
16	1		*FRONT GRILLE	Not Necessary	500.00 FS	*- FS
17	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,441.40	3,560.60
- List Item Discount on L Items 20.00/20.00% (S\$)	1,008.28	580.12
Total Parts (S\$)	5,433.12	2,980.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
3	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT O THE ACCIDENT	New	700.00	500.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
Gross Labour Cost (\$)			1,880.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >