

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21010118/UVF3E2

Date: 08/10/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29152764AT2

Claimant Vehicle No : SLG5958A

Insured Vehicle No : SME3681J

Date of Loss: 29/09/2021

Nature of Claim: TP

Claim No: 638202

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG5958A

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1717620

Reg. Date: 05/10/2016 (Man. Year: 2016)

Chassis No: ZGE206029654

Colour: Grey

Odometer: 294623 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,607.30	3,732.65	5,874.65	61.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	1,910.00	2,790.00	59.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,307.30</b>	<b>5,642.65</b>	<b>8,664.65</b>	<b>60.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>(S\$)</b>	14,307.30	4,500.00	9,807.30	68.55
<b>+ GST 7.00/7.00% (S\$)</b>	1,001.51	315.00	686.51	68.55
<b>Nett Amount (S\$)</b>	<b>15,308.81</b>	<b>4,815.00</b>	<b>10,493.81</b>	<b>68.55</b>

### INSPECTION

Date of Assignment: 30/09/2021

Date Inspected: 30/09/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG5958A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,288.10 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	145.40 FL	*145.40 FL
3	1		*TAILGATE	Badly Dented	1,742.00 FL	*1,642.00 FL
4	1		*TAILGATE OUTER HANDLE	Not Necessary	299.40 FL	*- FL
5	2		*TAILGATE REFLECTORS	Not Necessary	364.80 FL	*- FL
6	1		*TAILGATE INNER LOCK	Shorted	616.80 FL	*416.80 FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	386.20 FL	*322.30 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	567.30 FL	*367.30 FL
9	1		*REAR BUMPER	Dented / Torn	665.90 FL	*596.90 FL
10	2		*REAR BUMPER DAMPERS	Not Necessary	170.00 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	130.00 FL	*65.00 FL
12	2		*REAR BUMPER REFLECTORS	Not Necessary	120.00 FL	*- FL
13	1		*REAR END PANEL OUTER	Dented	842.00 FL	*542.00 FL
14	1		*REAR END PANEL LOWER	Repair	389.20 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	381.80 FL	*292.50 FL
16	2		*TAILLAMPS	Not Necessary	790.00 FL	*- FL
17	1		*REAR FENDER INNER TRIM BOARD O/S	Serviceable	645.20 FL	*- FL
18	1		*REAR FENDER UNDER SHIELD O/S	Not Necessary	121.50 FL	*- FL
19	1		*REAR FLOOR PANEL	Repair	1,410.80 FL	*- FL
20	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
23	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*TAILGATE LOGO	Necessary	60.00 FS	*60.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
28	1		*SET REAR FENDER INNER TRIM BOARD CLIPS O/S	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR FENDER UNDER SHIELD CLIPS O/S	Not Necessary	30.00 FS	*- FS
30	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,376.40</b>	<b>4,830.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,769.10	1,097.55
<b>Total Parts (\$\$)</b>	<b>9,607.30</b>	<b>3,732.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO REMOVE & REFIX CUSHION UPHOLSTERY	New	120.00	100.00
6	TO REMOVE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO REMOVE & REFIX REAR REVERSE CAMERA	New	100.00	0.00
8	TO SPRAY ANTI-RUST PROOFING	New	120.00	60.00
9	TO DIAGNSIS & REPROGRAMME SYSTEM	New	180.00	0.00
10	LABOUR FOR PANEL BEATING	New	1,800.00	600.00
11	TO PUTTY & SPRAY PAINTING	New	1,800.00	900.00
12	TO REMOVE & REFIX FUEL TANK	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,700.00</b>	<b>1,910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >