

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010119/AQCE2

Date: 19/11/2021

REFERENCE

Insured/Claimant:	YU QIAN	Policy No:	7210002173		
Date of Loss:	24/09/2021	Nature of Claim:	OD	Claim No:	2596152380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4006C		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM027753
Reg. Date:	11/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF56MA015362
Colour:	Blue	Odometer:	5191 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,859.00	4,096.00	16,763.00	80.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	2,272.00	3,700.00	61.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,831.00	6,368.00	20,463.00	76.27
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	26,031.00	5,568.00	20,463.00	78.61
+ GST 7.00/7.00% (S\$)	1,822.17	389.76	1,432.41	78.61
Nett Amount (S\$)	27,853.17	5,957.76	21,895.41	78.61

INSPECTION

Date of Assignment:	30/09/2021		
Date Inspected:	29/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$367.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,342.00 FS	*2,342.00 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	196.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	262.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	135.00 FS	*- FS
8	1		*FRONT BUMPER TRIM - RH	Not Necessary	48.00 FS	*- FS
9	1		*FRONT BUMPER TRIM - CENTER	Not Necessary	114.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,694.00 FS	*1,694.00 FS
11	1		*RADIATOR GRILLE BRACKET	* Check	17.00 FS	*- FS
12	1		*RADIATOR GRILLE TOP COVER	Not Necessary	166.00 FS	*- FS
13	1		*FRONT BUMPER SECURING PLATE1	Not Necessary	11.00 FS	*- FS
14	1		*FRONT BUMPER CAMERA	Not Necessary	1,141.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
16	1		*FRONT FOAM FILLER PIECE	Not Necessary	146.00 FS	*- FS
17	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	72.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
19	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
20	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
21	1		*LOCK CARRIER TOP BRACKET	Not Necessary	137.00 FS	*- FS
22	2		*LOCK CARRIER SUPPORT LH / RH	Not Necessary	58.00 FS	*- FS
23	1		*HORN - RH	Not Necessary	126.00 FS	*- FS
24	1		*HORN BRACKET - RH	Not Necessary	29.00 FS	*- FS
25	1		*FRONT PARKING AID SENSOR INNER (NPA)	Not Necessary	0.00 FS	*- FS
26	1		*FRONT PARKING AID SENSOR OUTER (NPA)	Not Necessary	0.00 FS	*- FS
27	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
28	1		*BONNET	Repair	3,312.00 FS	*- FS
29	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
30	1		*BONNET IMPACT PROTECTION - CENTER	Not Necessary	28.00 FS	*- FS
31	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	56.00 FS	*- FS
32	1		*BONNET STRIKER - RH	Not Necessary	50.00 FS	*- FS
33	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
34	1		*BOWDEN CABLE CENTER	Not Necessary	58.00 FS	*- FS
35	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
36	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
37	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	275.00 FS	*- FS
38	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
39	1		*FRONT WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
40	1		*LED HEADLIGHT - RH	Not Necessary	7,685.00 FS	*- FS
41	1		*LIFT CYLINDER - RH	Not Necessary	198.00 FS	*- FS
42	1		*HEADLIGHT PIPE (NPA)	Not Necessary	0.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE - RH	Not Necessary	32.00 FS	*- FS
44	1		*RADIATOR AIR GUIDE - RH	Not Necessary	16.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	22.00 FS	*- FS
47	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
48	1		*SUNDRIES	* Check	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **20,859.00** **4,096.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,972.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >