

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21010120/Kvf3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND Date: 08/10/2021 **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SMR 6423A** SKZ 28D Veh. Inspected Policy No. D21MTPV01005540 Coverage (\$) 0.00 Claim No. CMTD2102902/MYE Excess (\$) 0.00 **GRACE TEO Assign Date** 30/09/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA VELLFIRE (A) 2494 Make & Model C.C HIDDEN 2018 Engine No. Year of Reg. JTNGF3DH508018747 METALLIC PEARL WHITE Chassis No. Colour 168878 KM Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 235/50 R18 PIRELLI 2 mm PIRELLI L/H Front Tyre 235/50 R18 2 mm 235/50 R18 **PIRELLI** R/H Rear Tyre 3 mm **PIRELLI** L/H Rear Tyre 235/50 R18 3 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 25/09/2021 04/10/2021 ( 10:10 AM ) **Accident Date** Inspect Date / Time AH KOON MOTOR Survey held at BLK 1001 BUKIT MERAH LANE 3 #01-69 SINGAPORE 159718 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/SMO21010120/Kvf3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

**Estimate Days of Repair** 

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

5b.

KONG SENG CHEONG

**Licensed Appraiser** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser