

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21010124/EUF3E2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant:	LEE HSI MENG, IVAN	Policy No:	2070166219	
Date of Loss:	28/08/2021	Nature of Claim:	OD	Claim No: 6372847248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW5531B	Engine No:	10FKBL2679705
Make & Model:	CITROEN C5 AIRCROSS, 1.6 L SHINE (A)	Chassis No:	VR7A45GFRL059895
Reg. Date:	26/11/2020 (Man. Year: 2020)	Odometer:	13564 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,320.00	4,124.00	3,196.00	43.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,865.00	1,615.00	250.00	13.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,185.00	5,739.00	3,446.00	37.52
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	8,585.00	5,139.00	3,446.00	40.14
+ GST 7.00/7.00% (\$\$)	600.95	359.73	241.22	40.14
Nett Amount (\$\$)	9,185.95	5,498.73	3,687.22	40.14

INSPECTION

Date of Assignment:	30/09/2021	
Date Inspected:	30/09/2021 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FRONT BUMPER	Broken	1,502.00 F	*1,502.00 FL
3	1		*FR Bmpr GRILLE	Not Necessary	993.00 F	*- FL
4	1		*SET BRACKET	Necessary	109.00 F	*109.00 FL
5	1		*FINISHER BUMPER	Necessary	93.00 F	*93.00 FL
6	1		*FINISHER BUMPER	Crumpled	116.00 F	*116.00 FL
7	1		*BUMPER ABSORBER	Not Necessary	156.00 F	*- FL
8	1		*SET BRACKET	Not Necessary	109.00 F	*- FL
9	1		*REAR DUCT	Broken	167.00 F	*167.00 FL
10	1		*REAR DUCT	Broken	88.00 F	*88.00 FL
11	1		*BUMPER BRACKET	Broken	342.00 F	*342.00 FL
12	1		*BUMPER ABSORBER	Not Necessary	370.00 F	*- FL
13	1		*BUMPER ABSORBER	Not Necessary	499.00 F	*- FL
14	1		*FIXING STUD	Necessary	36.00 F	*36.00 FL
15	1		*FRONT LIGHT RH	Broken	770.00 F	*770.00 FL
16	1		*HDLIGHT SUPPORT RH COMPLEMENTA	Broken	72.00 F	*72.00 FL
17	1		*LIGHT MOULDING RH AV	Broken	90.00 F	*90.00 FL
18	1		*HEADLIGHT ASSY RH	Broken	691.00 F	*691.00 FL
19	1		*DISTRIB CHAMBER	Dented	840.00 F	*840.00 FL
20	1		*DIST CHB BRACKT	Bent	43.00 F	*43.00 FL
21	1		*DIST CHB BRACKT	Bent	43.00 F	*43.00 FL
22	1		*DIST CHB BRACKT	Not Necessary	43.00 F	*- FL
23	1		*FOG HEADLIGHT	Broken	128.00 F	*128.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					7,320.00	5,150.00
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	1,026.00
Total Parts (\$\$)					7,320.00	4,124.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER	New	500.00	500.00
2	REMOVE & INSTALL PARKING SENSOR	New	80.00	80.00
3	SPRAY PAINT FOR FRT BUMPER	New	380.00	380.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	50.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	225.00	225.00
6	RENEW INTERCOOLER	New	250.00	0.00
7	SPRAY PAINT FOR FRONT FENDER RH (Supplementary)	New	380.00	380.00
Gross Labour Cost (\$\$)			1,865.00	1,615.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >