

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010126/AEA3Q2**Date:** 12/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070134332
Claimant Vehicle No :	SJF1553P	Insured Vehicle No :	SLG3339A
Date of Loss:	23/09/2021	Nature of Claim:	TP
		Claim No:	9485218019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF1553P	Engine No:	M16A1305441
Make & Model:	SUZUKI SWIFT, 1.4 (A)	Chassis No:	ZC31S202487
Reg. Date:	21/05/2008 (Man. Year: 2007)	Odometer:	263271 km
Colour:	Yellow		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,269.48	3,859.66	3,409.82	46.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,150.00	1,950.00	62.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,369.48	5,009.66	5,359.82	51.69
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,369.48	4,000.00	6,369.48	61.43
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,607.45		

INSPECTION

Date of Assignment:	29/09/2021	
Date Inspected:	29/09/2021 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Cracked	1,275.00 FS	*1,000.00 FS
2	2		*FRONT BONNET HINGES	Not Necessary	75.40 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	66.30 FL	*- FL
4	1		*FRONT BONNET LOCK BRACKET	Not Necessary	50.70 FL	*- FL
5	1		*FRONT SUPPORT PANEL	Not Necessary	180.00 FL	*- FL
6	1		*FRONT HEADLAMP	N/S Cut	1,330.00 FL	*665.00 FL
7	1		*FRONT GRILLE	Cracked	180.00 FL	*180.00 FL
8	1		*FRONT BUMPER	Deformed	1,275.00 FS	*750.00 FS
9	2		*FRONT BUMPER SIDE HOLDER	Necessary	80.60 FL	*80.60 FL
10	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	180.00 FL	*- FL
11	2		*FRONT BUMPER LOWER SIDE GRILLE	Not Necessary	200.00 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	247.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	156.00 FL	*156.00 FL
14	1		*FRONT BUMPER SPONGE	Not Necessary	105.00 FL	*- FL
15	1		*FRONT NUMBER PLATE GARNISH	Deformed	55.00 FL	*55.00 FL
16	1		*AIRCOND CONDENSER	Not Necessary	816.40 FL	*- FL
17	1		*REAR BUMPER	Deformed	713.70 FL	*585.00 FL
18	1		*REAR BUMPER LOWER LIP	Cracked	722.50 FS	*500.00 FS
19	1		*REAR BUMPER LOWER RH REVERSE LAMP	Cracked	78.00 FL	*78.00 FL
20	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*30.00 FS
21	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
22	1		*SET FRONT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
					Sub Total (S\$)	7,946.60 4,129.60
					- List Item Discount on L Items 15.00/15.00% (S\$)	677.12 269.94
					Total Parts (S\$)	7,269.48 3,859.66

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
2	REMOVE & REFIX AIRCOND FILL IN GAS	New	150.00	0.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,500.00	700.00
4	RESPRAY PAINTING	New	1,300.00	400.00
Gross Labour Cost (\$\$)			3,100.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >