



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21010137/Btf3n2	Date: 15/10/2021
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SKX 2000E	Veh. Inspected	SMV 8012T
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10011905/EE	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	30/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ CLA180 COUPE	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	W1K1183842N122109	Colour	BLACK
	Odometer	12378 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE	5 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE	5 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE	5 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	29/09/2021	Inspection Date	05/10/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	