

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21010143/KTF3N2**Date:** 10/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001492381		
Claimant Vehicle No :	SLC6683G	Insured Vehicle No :	YQ1688Z		
Date of Loss:	27/09/2021	Nature of Claim:	TP	Claim No:	263265

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC6683G		
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Engine No:	3ZRB760385
Reg. Date:	23/05/2016 (Man. Year: 2016)	Chassis No:	ZSU600075490
Colour:	Metallic Dark Brown	Odometer:	75648 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R18	Rear Tyre Size:	225/60R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,969.30	6,359.47	609.83	8.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	1,030.00	200.00	16.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,199.30	7,389.47	809.83	9.88
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	8,199.30	5,900.00	2,299.30	28.04
+ GST 7.00/7.00% (S\$)	573.95	413.00	160.95	28.04
Nett Amount (S\$)	8,773.25	6,313.00	2,460.25	28.04

INSPECTION

Date of Assignment:	30/09/2021	
Date Inspected:	06/10/2021 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Dec 2021)	
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC6683G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled/Dented	602.10 FL	*602.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	521.70 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Cracked	112.20 FL	*112.20 FL
4	1		*FRONT BUMPER CENTRE LOWER GRILLE	Cut/Dented	297.30 FL	*297.30 FL
5	1		*FRONT BUMPER LOWER SPOILER	Dented/Cut	340.20 FL	*340.20 FL
6	1		*FRONT BUMPER TOP BEAM	Buckled	301.10 FL	*301.10 FL
7	1		*FRONT BUMPER LH SIDE RETAINER	Serviceable	115.20 FL	*- FL
8	10		*FRONT BUMPER CLIP	Necessary	45.00 FL	*45.00 FL
9	1		*BONNET	Bent	1,983.90 FL	*1,983.90 FL
10	1		*BONNET CHROME MOULDING	Cracked	279.30 FL	*279.30 FL
11	1		*FRONT GRILLE ASSY	Scratched	590.60 FL	*590.60 FL
12	1		*HEADLAMP LH	Mtg Cracked	3,511.90 FL	*3,511.90 FL
13	1		*HEADLAMP LH TOP PANEL	Repair	176.20 FL	*- FL
14	1		*HEADLAMP LH LOWER PANEL	Distorted	127.40 FL	*127.40 FL
15	1		*HEADLAMP LH SPONGE	Cracked	56.70 FL	*56.70 FL
16	1		*SET RADIATOR LH SIDE GARNISH	Dented	231.60 FL	*231.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	9,292.40	8,479.30
- List Item Discount on L Items 25.00/25.00% (S\$)	2,323.10	2,119.83
Total Parts (S\$)	6,969.30	6,359.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,LH HEADLAMP;KNOCKING & REPAIR FRT SUPPORT PANEL & REALIGN LH FENDER THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY FRT BUMPER,BONNET,FRT LH FENDER,FRT PANEL & ALL AFFECTED AREAS	New	700.00	600.00
3	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,230.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >