

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21010153/AQF3N2**Date:** 10/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070055229
Claimant Vehicle No :	GBA7196T	Insured Vehicle No :	GBJ4678S
Date of Loss:	28/09/2021	Nature of Claim:	TP
		Claim No:	3053076293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA7196T		
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Engine No:	1KD1668923
Reg. Date:	24/10/2007 (Man. Year: 2007)	Chassis No:	JTFAT35YX03001240
Colour:	Silver	Odometer:	442647 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75R15C	Rear Tyre Size:	155R12
Front Left Side:	Kenda 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Kenda 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,334.20	2,138.22	4,195.98	66.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,380.00	1,000.00	42.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,714.20	3,518.22	5,195.98	59.63
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	8,714.20	2,800.00	5,914.20	67.87

INSPECTION

Date of Assignment:	01/10/2021	2020 Spray Painting Pte Ltd (HQ) 53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL PARK Singapore 408934
Date Inspected:	01/10/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	589.40 F	*- FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	450.20 F	*- FL
3	1		*FRONT GRILLE	Cracked	564.10 F	*564.10 FL
4	2		*HEADLAMP	Cracked	1,292.20 F	*1,292.20 FL
5	1		*FRONT PANEL	Repair	1,019.50 F	*- FL
6	1		*FRONT PANEL TOYOTA LOGO	Necessary	65.90 F	*65.90 FL
7	1		*FRONT PANEL DYNA WORDING	Necessary	79.20 F	*79.20 FL
8	1		*FRONT RH CORNER PANEL	Distorted	264.30 F	*264.30 FL
9	1		*FRONT RH CORNER PANEL TOP GARNISH	Cut	122.70 F	*122.70 FL
10	1		*FRONT RH DOOR	Repair	1,310.80 F	*- FL
11	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
12	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*FRONT RH DOOR COMPANY ADDRESS STICKER	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT RH DOOR ADVERTISEMENT STICKERS	Necessary	300.00 FS	*150.00 FS
15	1		*FRONT WIPER PANEL SIDE GARNISH RH	Cracked	195.90 F	*195.90 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					6,334.20	2,784.30
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	646.08
Total Parts (\$\$)					6,334.20	2,138.22
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	500.00
2	SPRAY PAINTING	New	1,000.00	850.00
3	WIRING	New	50.00	30.00
4	TO REMOVE FRONT WINDSCREEN	New	180.00	0.00
5	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
Gross Labour Cost (\$)			2,380.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >