

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21010155/GUF3N2**Date:** 29/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800145516
Claimant Vehicle No :	SKN6301M	Insured Vehicle No :	SMG2395G
Date of Loss:	29/09/2021	Nature of Claim:	TP
		Claim No:	4470200607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN6301M		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CXS046157
Reg. Date:	30/06/2014 (Man. Year: 2013)	Chassis No:	WAUZZZ8VXEA090063
Colour:	Black	Odometer:	98595 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/10/2021	
Date Inspected:	01/10/2021	Inspected At: King's Auto Repair & Service Pte Ltd (HQ) BLK 176 SIN MING DRIVE, #02-10 Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$44,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER LH	Cracked	0.00 F	*- F
4	1		*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
6	1		*FRT LH FENDER	Repair	0.00 F	*- F
7	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
8	1		*FRT LH WHEEL RIM	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >