

Date : 12 April 2018

To : **NTUC Income Insurance Co-operative Limited**
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn : Mr Yon Kai Jie

AJAX Inspection Services Pte Ltd

120 Lower Delta Road
#08-08, Cendex Centre
Singapore 169208

Tel: +65 6255 0808

Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No – AV14131

Company Reg No -201318067R

GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/0963221-003 ✓
OUR REF : AVS2017-12762/WH
TP VEHICLE NO : FBL1182P ✓
CLAIM TYPE : PRE-REPAIR SURVEY
DATE OF SURVEY : 06 October 2017

No.	Description	Amount (\$S)
1	Professional fee	250.00

Subtotal 250.00
GST 7.00% 17.50
Total 267.50

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Yon Kai Jie

Assign Date:	06/10/2017	Survey Date:	06/10/2017	Our Ref:	AVS2017-12762/WH
Accident Date:	26/09/2017	TP Policy No:	TBA	Your Ref:	MT/0963221-003
Place of Survey:	Equator Brotherhood 25 Kaki Bukit Road 4 #03-79 Synergy @ KB Singapore 417800			Claim Type:	Third Party
				Claimant:	Muhammad Zulhakim Bin Bakar

Description of Vehicle:

Veh. No:	FBL1182P	Make/Model:	Honda CBR1000RR Fireblade
Colour:	Multi-colored	Engine No:	SC59E2508627
Engine Capacity:	999cc	Chassis No:	JH2SC59A4GK800458
Odometer:	8902	Reg. Date:	09/10/2016

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	NA
Handbrake:	NA	Footbrake:	NA	Paint work:	Good
Tyre Make:	Bridgrstone				
Front Tyre Size:	120/70/R17	Front Side:	4mm		
Rear Tyre Size:	195/50/R17	Rear Side:	4mm		

Description of Damage:

The vehicle sustained damage on the front, rear and right portion.

The exhaust pipe, front fairing, engine cover, headlamp cowl, front mudguard and handle bar were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$2,750.00 with approximately four (4) working days to complete. However, no finalisation was agreed with the repairer.

All the stated damage are subject to consistency of the mentioned accident.



Adjuster: Lee Wee Ho
Motor Appraiser

COMPLETED 11 APR 2018

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Adjustment of Repair Cost for Vehicle: **FBL1182P** **Our Ref:** AVS2017-12762/WH

No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Honda swing arm	Not necessary	2,000.00	--
2	2	Honda front brake disc @ \$400.00	Not necessary	800.00	--
3	2	Honda front fork @ \$1,700.00	Repair	3,400.00	--
4	1	Honda tripple clamps (top)	Not necessary	300.00	--
5	1	Honda tripple clamps (bottom)	Not necessary	700.00	--
6	1	Hona steering cone bearing	Not necessary	140.00	--
7	1	Honda rear suspension	Not necessary	1,700.00	--
8	1	Honda suspension linkage set	Repair	--	--
9	1	Honda headlight set	Not necessary	1,450.00	--
10	1	Honda head fairing	Cracked	800.00	800.00
11	1	Honda mirror (right)	Grazed	300.00	300.00
12	1	Honda rider footrest bracket (right)	Not necessary	150.00	--
13	1	Honda rider footrest (right)	Damaged	90.00	90.00
14	1	Honda clutch case	Cut	350.00	350.00
15	1	Honda clutch gasket	Necessary	20.00	20.00
16	1	Honda bar end balancer (right)	Grazed	25.00	25.00
17	1	Honda brake lever	Grazed	70.00	70.00
18	2	Honda front wheel bearing @ \$35.00	Not necessary	70.00	--
19	2	Honda rear wheel bearing @ \$35.00	Not necessary	70.00	--
20	1	Honda swing arm bushing set	Not necessary	80.00	--
21	1	Honda swing arm shaft	Not necessary	120.00	--
22	1	Honda handle bar (right)	Bent	200.00	200.00
23	1	Rozima crash slider	Grazed	180.00	180.00
24	1	Zero gravity windshield (front)	Cracked	230.00	230.00
Sub Total:				13,245.00	2,265.00
Discount (less 10%):				1,324.50	226.50
				11,920.50	2,038.50

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:			FBL1182P	Our Ref: AVS2017-12762/WH	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
Special Nett Items					
1	3	Motul 300V engine oil @ \$30.00	Necessary	90.00	80.00
2	1	Rear number plate	Bent	15.00	15.00
3	1	Bodis twin exhaust (Approved)	Repair	2,850.00	--
Sub Total:				2,955.00	95.00
Total Parts Price:				14,875.50	2,133.50

Labour Cost			
1	To remove & replace swing arm, rear suspension, front & rear wheel bearing, axle shaft, front fork, tripple clamps, steering cone, front brake disc.	480.00	--
2	To remove & replace above body damaged parts and check lighting system.	500.00	400.00
3	To respray paint on the affected area.	1,200.00	600.00
4	To conduct chasss aligment.	280.00	200.00
5	To remove and repair, balancing and respray.	280.00	--
6	Towing - from traffic police compound to workshop.	35.00	35.00
7	Towing - (2 way trip workshop to accident reporting)	70.00	70.00
8	Exhaust inspection.	95.00	--
Sub Total:		2,940.00	1,305.00
Grand Total:		17,815.50	3,438.50