



Advanced Automotive Consultancy Pte Ltd

159, Yishun St 11, #04-166, S(760159)
Business Regn No : 201416413W
Tel/ Fax no: 67568321

Tax Invoice

MUHAMMAD ZULHAKIM BIN BAKAR

Invoice No. : AAC 18 FEB 04

c/o EQUATOR BROTHERHOOD
Blk 25, Kaki Bukit Rd 4 Synergy@KB, #03-79
Singapore 417800

Invoice Date : 10-Feb-18

Terms : 30 Days

Ref No. : TP/FBL1182P/Equator/1017/01

Vehicle No. : FBL1182P

Date of Accident : 26-Sep-17

Date of Survey : 03-Oct-17

Description

Amount

(1) Survey Of Vehicle	SGD \$520.00
- A set of survey report	
- Correspondence & Consultation	
(2) Transportation Charges including resurvey	SGD \$120.00
(3) Attached Photographs (96 pcs)	SGD \$96.00

Total SGD \$736.00

GRAND TOTAL SGD \$736.00

E. & O.E.

Cheque should be crossed and made payment to "Advanced Automotive Consultancy Pte Ltd"



Authorised By



Advanced Automotive Consultancy Pte Ltd

Bussiness Regn No: 201416413W

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

1 REFERENCE			
Our reference no	:	TP/FBL1182P/Equator/1017/01	
Date of request	:	3-Oct-2017	
Date of survey	:	3-Oct-2017	
Date of accident	:	26-Sep-2017	
Requested by	:	MUHAMMAD ZULHAKIM BIN BAKAR C/o , Blk 25 Kaki Bukit Rd 4 Synergy@KB, #03-79.Singapore 417800	
Type of claim	:	Third party	
Workshop	:	EQUATOR BROTHERHOOD Blk 25, Kaki Bukit Rd 4 Synergy@KB, #03-79 Singapore 417800	
2 DETAILS OF VEHICLE			
Registration No.	:	FBL1182P	
Make & Model	:	HONDA CBR1000RR FIREBLADE	
Date of registration	:	9-Jun-2016	
Engine No.	:	SC59E2508627	
Engine Capacity	:	999 CC	
Chassis No.	:	JH2SC59A4GK800458	
Speedometer reading	:	8,901KM	
Colour	:	ORANGE	
3 STATIC CHECK			
Steering	:	In order	Paintwork : Good
Footbrake	:	In order	Modification : Nil
Handbrake	:	In order	General condition : Good
4 TYRE CONDITION			
		<u>Nearside/Make</u>	<u>Size</u>
Front tyre	:	3mm/Bridgestone	120/70ZR17
Rear tyre	:	3mm/Bridgestone	190/50ZR17
5 POINT OF IMPACT			
The said vehicle has sustained an impact damages on the front, RH side and rear portion. Kindly refer to the attached photographs for more detail of the damages.			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Advanced Automotive Consultancy Pte Ltd

Annex A : Assesement / Adjustment on SpareParts

TP/FBL1182P/Equator/1017/01

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Honda swing arm	distorted	1	\$2,000.00	10%	\$1,800.00
2	Honda front brake disc @ \$400.00	warped	2	\$800.00	10%	\$720.00
3	Honda front fork @ \$1,700.00	leak/distorted	2	\$3,400.00	10%	\$3,060.00
4	Honda tripple clamps (top)	distorted	1	\$300.00	10%	\$270.00
5	Honda tripple clamps (bottom)	distorted	1	\$700.00	10%	\$630.00
6	Honda steering cone bearing	distorted/necessary	1	\$140.00	10%	\$126.00
7	Honda rear suspension	distorted	1	\$1,700.00	10%	\$1,530.00
8	Honda suspension linkage set	repair	1	\$220.00	100%	\$0.00
9	Honda headlight set	grazed	1	\$1,450.00	10%	\$1,305.00
10	Honda head fairing	broken	1	\$800.00	10%	\$720.00
11	Honda mirror (right)	grazed	1	\$300.00	10%	\$270.00
12	Honda rider footrest bracket (right)	distorted	1	\$150.00	10%	\$135.00
13	Honda rider footrest (right)	grazed	1	\$90.00	10%	\$81.00
14	Honda clutch case	grazed	1	\$350.00	10%	\$315.00
15	Honda clutch gasket	necessary	1	\$20.00	10%	\$18.00
16	Honda bar end balancer (right)	grazed	1	\$25.00	10%	\$22.50
17	Honda brake lever	grazed/bent	1	\$70.00	10%	\$63.00
18	Honda front wheel bearing @ \$35.00	necessary/rattle	2	\$70.00	10%	\$63.00
19	Honda rear wheel bearing @ \$35.00	necessary/rattle	2	\$70.00	10%	\$63.00
20	Honda swing arm bushing set	necessary	1	\$80.00	10%	\$72.00
21	Honda swing arm shaft	distorted	1	\$120.00	10%	\$108.00
22	Honda handle bar (right)	bent	1	\$200.00	10%	\$180.00
23	Rozima crash slider	grazed	1	\$180.00	10%	\$162.00
24	Zero gravity windshield (front)	holder cracked	1	\$230.00	10%	\$207.00
				\$13,465.00		\$11,920.50
S/Nett Items						
1	Motul 300V engine oil @ \$30.00	necessary	3	\$90.00		\$90.00
2	Rear number plate	dented	1	\$15.00		\$15.00
3	Bodis twin exhaust (Approved)	grazed	1	\$2,850.00		\$2,850.00
				\$2,955.00		\$2,955.00
Total for Spare Parts:				\$16,420.00		\$14,875.50

Advanced Automotive Consultancy Pte Ltd

TP/FBL1182P/Equator/1017/01

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Equator Brotherhood estimated repair cost is **S\$20,070.00** and we have adjusted it to **S\$17,815.50** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.


The repairer have agreed to undertake the repairs on a contract lump sum of **S\$15,100.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 7 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,



Henry Low
Automotive License Appraiser
CMTM, DMTM, IPTM (UNF)