

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21010162/EES3Q2
Date: 27/12/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447	
Claimant Vehicle No :	PA6982G	Insured Vehicle No :	SLL7074K	
Date of Loss:	30/09/2021	Nature of Claim:	TP	Claim No: MFL2021D0004439

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA6982G		
Make & Model:	ISUZU LT134P, 7.8 D (A)	Engine No:	6HK1451500
Reg. Date:	12/06/2007 (Man. Year: 2007)	Chassis No:	JALLT134P77000098
Colour:	Multi-colour	Odometer:	653966 km
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/50 R27.50	Rear Tyre Size:	295/50 R27.50
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,934.90	2,690.00	8,244.90	75.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,450.00	1,000.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,384.90	4,140.00	9,244.90	69.07
Approved Total (Overridden) (S\$)		3,300.00		

Nett Amount (S\$)	13,384.90	3,300.00	10,084.90	75.35
+ Loss of Use (5.0 x S\$180.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,207.49		

INSPECTION

Date of Assignment: 01/10/2021

Date Inspected: 04/10/2021

Inspected At:

Serve You Motor Service (HQ)
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265
 Singapore 569536

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Dec 2021)		
Parts:	N/A	ISUZU LT134P 7.8 D (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for PA6982G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	2,800.00 FL	*1,750.00 FL
2	2		*REAR BUMPER SIDE BRACKET	Bent	1,300.00 FL	*200.00 FL
3	1		*REAR BUMPER BIM	Not Necessary	880.00 FL	*- FL
4	1		*REAR BUMPER INNER REINFORCEMENT	Bent	868.00 FL	*500.00 FL
5	1		*REAR INNER CENTRAL PANEL BRACKET	Bent	1,550.00 FL	*350.00 FL
6	1		*REAR ENGINE COMPARTMENT COVER WITH GRILLE	Not Necessary	3,350.00 FL	*- FL
7	1		*REAR ENGINE COMPARTMENT COVER -INTERLOCK	Not Necessary	365.00 FL	*- FL
8	1		*REAR ENGINE COMPARTMENT COVER -OUTER HANDLE	Not Necessary	198.00 FL	*- FL
9	1		*REAR ENGINE COMPARTMENT COVER -INNER FRAME	Not Necessary	580.00 FL	*- FL
10	1		*REAR NUMBER PLATE	Cut	65.00 FS	*45.00 FS
11	1		*REAR 60KM/H STICKER	Necessary	30.00 FS	*25.00 FS
12	2		*REAR NO PLATE LAMP	Broken	138.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,124.00	2,970.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,189.10	280.00
Total Parts (\$)	10,934.90	2,690.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION TO PANEL BEATING ,RESHAPE ,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,500.00	600.00
2	SUPPLY SPRAY PAINT MATERIAL (MULTI PURPOSR COLOR) AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT DAMAGED AREA	New	950.00	850.00
Gross Labour Cost (S\$)			2,450.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >