

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010163/UPS3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100012436-14
Claimant Vehicle No :	GBL5026G	Insured Vehicle No :	SBL8899J
Date of Loss:	22/09/2021	Nature of Claim:	TP
		Claim No:	2206731423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL5026G		
Make & Model:	NISSAN NV200, 1.6 VANETTE DX (A)	Engine No:	HR16181982D
Reg. Date:	16/09/2021 (Man. Year: 2020)	Chassis No:	VM20164154
Colour:	Grey	Odometer:	621 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 9 mm	Rear Left Side:	Toyo 9 mm
Front Right Side:	Toyo 9 mm	Rear Right Side:	Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,885.50	849.00	2,036.50	70.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	520.00	480.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,885.50	1,369.00	2,516.50	64.77
+ GST 7.00/7.00% (S\$)	271.99	95.83	176.16	64.77
Nett Amount (S\$)	4,157.49	1,464.83	2,692.66	64.77
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,680.83		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment:	01/10/2021	
Date Inspected:	01/10/2021	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT HEADLAMP	Serviceable	658.10 F	*- FN
2	1		*FRONT RIGHT HEADLAMP GARNISH	Cut	425.30 F	*368.50 FN
3	1		*FRONT BUMPER	Cut	675.20 F	*541.50 FN
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	1		*FRONT BUMPER RETAINER (RIGHT)	Not Necessary	34.00 F	*- FN
6	1		*REINFORCEMENT	Not Necessary	1,062.90 F	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	2,885.50	940.00
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	91.00
Total Parts (S\$)	2,885.50	849.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	50.00	20.00
2	ANTI RUST PROOF	New	50.00	0.00
3	PANEL BEATING	New	500.00	350.00
4	PAINT WORK	New	400.00	150.00
Gross Labour Cost (\$\$)			1,000.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >