

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG121010164/KTF3N2**Date:** 07/06/2022REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG21002342
<b>Claimant Vehicle No :</b>	SMX6803E	<b>Insured Vehicle No :</b>	SGG2225K
Date of Loss:	22/09/2021	Nature of Claim:	TP
		Claim No:	CDMPG21001929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMX6803E</b>	Engine No:	2ZR2H26080
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU703092902
Reg. Date:	26/01/2021 (Man. Year: 2020)	Odometer:	69632 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,982.25	2,529.57	1,452.68	36.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,670.00	440.00	8,230.00	94.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,652.25</b>	<b>2,969.57</b>	<b>9,682.68</b>	<b>76.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	885.66	207.87	677.79	76.53
<b>Nett Amount (S\$)</b>	<b>13,537.91</b>	<b>3,177.44</b>	<b>10,360.47</b>	<b>76.53</b>

INSPECTION

Date of Assignment:	01/10/2021		
Date Inspected:	05/10/2021	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$2,969.58

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX6803E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,FRONT BUMPER	Repair	521.00 FL	*- FL
2	1		*BRACKET,FRONT BUMPER EXTENSION MOUNTING	Serviceable	110.50 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Repair	716.60 FL	*- FL
4	1		*ABSORBER,FRONT BUMPER ENERGY	Cracked	80.20 FL	*80.20 FL
5	1		*COVER,FRONT BUMPER HOLE,LH	Serviceable	30.20 FL	*- FL
6	1		*GRILLE SUB-ASSY,RADIATOR	Dented	422.50 FL	*422.50 FL
7	1		*GRILLE,RADIATOR,LOWER NO 1	Serviceable	178.60 FL	*- FL
8	1		*EMBLEM ASSY,RADIATOR GRILLE	Necessary	105.80 FL	*105.80 FL
9	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	*50.00 FS
10	1		*FRT NUMBER PLATE WITH MOULDING	Dented	200.00 FS	*45.00 FS
11	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
12	1		*UNIT ASSY,HEADLAMP LH	Mtg Cracked	2,637.60 FL	*2,637.60 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,183.00	3,341.10
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,200.75	811.53
Total Parts (\$\$)					3,982.25	2,529.57

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
3	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
4	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	220.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
13	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
14	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
15	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,670.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >